

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
811 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
Lease Designation and Serial No.
LC-068282-B

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other P & A

2. Name of Operator

Hanson Operating Company, Inc.

3. Address and Telephone No.

P.O. Box 1515, Roswell, NM 88202-1515

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

NW 1/4 SE 1/4 Unit J 1650' FSL & 2310' FEL Sec. 25 T26S R31E

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Hanson Federal #7

9. API Well No.

30-015-05873

10. Field and Pool, or Exploratory Area

North Mason Delaware

11. County or Parish, State

Eddy

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On October 15, 1996 the above well was plugged & abandoned as follows:

10-15-96 MIRU-NDWH-NUBOP set 5 1/2" CIBP @ 4130' POH-CION

10-16-96 Dump 35' cement on top of CIBP RIH with tubing to 4050' circulated 10# mud POH to 3500' spot 25 sxs cement POH rig to cut casing cut @ 1900' could not pull, pressure test cut to 500# spot 25 sxs cement @ 1950'-1750' CION

10-17-96 Open well cut casing @ 1020' POH RIH to 1070' Spot 85 sxs cement WOC Tag @ 830' POH spot 20 sxs @ 50' to surface rig down

10-18-96 Install dry hole marked- move rigs

Pet ID-1
12-22-96
PFA

14. I hereby certify that the foregoing is true and correct

Signed Betsy Speer

Title Production Analyst

Date 10-22-96

(This space for Federal or State office use)

Approved by (ORIG. SGD.) ALEXIS C. SWOBODA
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date 11/6/96