

N. M. O. C. COPY  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRI  
(Other instructio  
verse side)

ATE  
n re

Form approved.  
Budget Bureau No. 42-R1424.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. NAME OF OPERATOR <b>TEXACO Inc.</b></p> <p>3. ADDRESS OF OPERATOR <b>P. O. Box 728, Hobbs, New Mexico 88240</b></p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <b>Well is located 433' FSL &amp; 1980' FEL of Section 26, T-26-S, R-31-E, Unit Letter '0', Eddy County, New Mexico</b></p> <p>14. PERMIT NO. <b>Regular</b></p> <p>15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>3142' (GR)</b></p>		<p>5. LEASE DESIGNATION AND SERIAL NO. <b>LC-070869</b></p> <p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME -</p> <p>7. UNIT AGREEMENT NAME -</p> <p>8. FARM OR LEASE NAME <b>E.D. White Fed. NCT-1</b></p> <p>9. WELL NO. <b>3</b></p> <p>10. FIELD AND POOL, OR WILDCAT <b>NEEDLE</b></p> <p>11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec. 26, T-26-S, R-31-E</b></p> <p>12. COUNTY OR PARISH <b>Eddy</b></p> <p>13. STATE <b>New Mexico</b></p>
---	--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) **Deepen 50' in Same Zone** ☒

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**RECEIVED**

1. Rig Up. Install BOP.
2. Drill Deeper 4128' (TD) to 4178', proposed new TD.
3. Log Well. Set packer at 4050'.
4. Acid/frac open-hole 4110'-4178' w/2400 gal. 15% NE Acid & 18,000 gal. Emulsifrac containing 25#/1000 gal. Adomite & 2# 20/40 Sand per gal. in 6-equal stages using 70# unibeads between stages.
5. Flush last stage w/30 bbl. lease crude. Swab.
6. Install pumping equipment. Test & return to production.

**JUL 21 1976**

**O. C. C.  
ARTESIA, OFFICE**

**RECEIVED**

**JUL 19 1976**

**U. S. GEOLOGICAL SURVEY,  
ARTESIA, NEW MEXICO**

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Asst. Dist. Supt.

DATE 7-14-76

(This space for Federal or State office use)

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

**APPROVED**  
**JUL 21 1976**  
**L. E. BECKMAN**  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side