

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-10843

5. Indicate Type of Lease STATE ☒ FEE ☐

6. State Oil / Gas Lease No. K 4562

7. Lease Name or Unit Agreement Name COTTON DRAW UNIT

8. Well No. 65

9. Pool Name or Wildcat 77053 SWD
PADUCA MORROW FORMATION
Cherry Canyon

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3455'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER SWD

2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator 205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter G : 1980 Feet From The NORTH Line and 1980 Feet From The EAST Line
Section 2 Township 25S Range 31E NMPM EDDY COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ CONVERT TO SWD ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-02-98: MIRU. NDTREE. NUBOP.
3-03-98: TIH W/BIT, CSG SCRAPER. RAN BIT TO 8175'. TIH W/PKR, & TBG TO 1329'.
3-04-98: TIH W/TBG. SET PKR @ 8334'. REL PKR. TIH W/TBG OPEN ENDED TO 11443'. TAG UP. RAISE TBG TO 11437'.
3-05-98: SPOT 186 BBLS 10# BRINE GEL FR 11443-8240. TIH W/CIBP & SET @ 8250'. PULL TBG TO 8244'.
3-06-98: SPOT 20 SX CL H CMT 8250-8180 NEW PBD @ 8180'. TIH W/LOG TOOL. RUN CBT/CCL/GR FR 6000-3000'.
3-07-98: TIH W/GUNS & PERF IN CHERRY CANYON FORMATION FR 5326-50,5413-41,5465-81,5702-14.
3-09-98: RAN PKR & SN ON TBG. SET PKR @ 5277'. ACIDIZED CSG PERFS 5326-5714' PADUCA DELAWARE CHERRY CANYON ZONE W/3000 GALS 15% NEFE. REL PKR. RESET @ 5277'. SWAB 1 HR. FL @ 400 FROM SURF. END FL @ 4800'.
3-10-98: MOVE PKR TO 4803'. RESET PKR @ 4803'. PMP 50 BBLS DN CSG. RESET PKR @ 4803'. RU REV EQPT.
3-11-98: START PUMPING FORMATION WTR FROM CDU #76. PUMP 9 BBLS & CAUGHT PSI.
3-12-98/3-15-98: CONTINUE INJ TESTING.
3-16-98: REL PKR. MI & UNLOAD PROD TBG. RAN PKR, NIP, ON/OFF TOOL. PU 3 1/2" TBG.
3-17-98: FLANGE UP WH. PUMP 300 BBLS PKR FLUID. NDWH. NUBOP.
3-18-98: TIH W/PKR, IPC, ON/OFF TOOL, PROF NIP, TBG. SET PKR @ 5262.94'. CIRC W/300 BBLS PKR FLUID.
3-19-98: NDBOP. NUWH. INSTL WH. PSI CSG TO 500 PSI FOR 30 MIN FOR NMOC. RIG DOWN.
FINAL REPORT

ADMINISTRATIVE ORDER SWD-699

THIS REPORT IS BEING SENT IN PER REQUEST OF BOBBY HILL - ENGINEERING ASSISTANT - TEXACO

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 6/29/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 393-7100

(This space for State Use)

APPROVED [Signature] TITLE Field Rep II

DATE 9/12/2000