

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN T
(Other instru- s on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0472258

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Government M

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

28-25S-24E

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, GR, etc.)

3779 D.F.

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Temporarily Abandonment

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Subsequent Report of Temporary Abandonment - As previously reported: the Morrow sand was tested through 20 holes 7039-44 and 16 holes 7048-52 at rate of 1,367 MCF/day, no distillate no water, FTP 400 psi on 20/64". Temporarily abandoned Morrow sand by setting C.I. bridge plug at 7000' with 2 sacks cement on top of plug to 6984'.

Subsequently - PBD 6984. Perforated Atoka 12 holes 6816-6822. Set packer at 6770'. Swabbed well dry. Acidized Atoka with 2000 gal. at rate of 3 B/M at 4600 psi. Total load 76 bbls. Recovered 50 bbls. of load and well swabbed dry. Pulled tbg. and packer. Atoka perforations were left open.

PBD 6984. Perforated Strawn limited entry with holes at 5892-95-97-98-99, 5905-07-09 and 15. Set retrievable bridge plug at 5949 and packer at 5854'. Swabbed well dry. Acidized Strawn with 3000 gal. at rate of 4 B/M at 4600 psi. Total load 96 bbls. Recovered 48 bbls. of load and well swabbed dry. Weak blow of gas TSTM. Pulled retrievable bridge plug and packer. Strawn perforations were left open.

PBD 6984. On 6/14/67 the well was temporarily abandoned leaving the dry Atoka and Strawn perforations open. Ran tubing open ended to 6984. Displaced hole with mud laden fluid. Laid down xmas tree. Installed padlocked valves on well head.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

District Clerk

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED
JUL 17 1967
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, N. M.

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.