JITED STATES SUBMIT IN T ACATE\*

DEF	NM-6708	
the not use this form fo	NOTICES AND REPORTS ON WELLS or proposals to drill or to deepen or plug back to a different reservoir. APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR THIBE NAME
1.		7. UNIT AGREEMENT NAME
OIL GAS WELL GAS	OTHER Dry hole	
2. NAME OF OPERATOR	8. FARM OR LEASE NAME	
Union Oil Compar	Verse Federal 7	
3. ADDRESS OF OPERATOR	9. WELL NO.	
P.O. Box 671 - 3	11	
4. LOCATION OF WELL (Report 1	10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface	Wildcat	
760' FNL & 2230	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA	
		Sec. 7, T-25S, R-22E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 12. STATE
	5909.7' GR	Eddy N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	MULTIPLE COMPLETE  ABANDON*  CHANGE PLANS	X	WATER SHUT-OFF  FRACTURE TREATMENT  SHOOTING OR ACIDIZING  (Other)  (Note: Report results of macing the completion of Recompletion is recompleted.)	REPAIRING WELL  ALTERING CASING  ABANDONMENT*  Itiple completion on Well Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled 7-7/8" hole to 7360' TD. 2-9 to 3-13-73:

Proposed plugging procedure:

- 6600 - 6500' 50 sx - 5600 - 5400' - 4600 - 45001 - 3000 - 2900' xa 0č 1550 - 1450' 100 sx 10 sx 20' - Surface

Verbal approval from Mr. R. L. Beekman, Artesia.

18. I hereby certify that the foregoing is true and correct Multiple the Surry Alleche (This space for Federal or State, office use) APPROVAL, IF ANY: \*See Instructions on Reverse Side