

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

3. Lease Designation and Serial No
Fed. NM-0525452A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

Gas Storage Well

2. Name of Operator

El Paso Natural Gas Co.

3. Address and Telephone No.

P.O. Box 1492, El Paso, Texas 79978 (915) 541-2600

4. Location of Well (Fossage, Sec., T., R., M., or Survey Description)

1980' FNL & 1980' FWL
SEC. 3, T-26-S, R-24-E

7. If Unit or CA, Agreement Designation

8. Well Name and No.

W.I. #4

9. API Well No.

10. Field and Pool, or Exploratory Area

Wsh. Rnch Mor.

11. County or Parish, State

Eddy Co., N.M.

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
Inspect and Cement

(From: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is discontinuously drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- | | |
|--|--|
| 1) MI & RU PU & Surface Equipment | 14) Run Bit & Drill Collars & Drill Out Cement |
| 2) Kill Well | 15) Pressure-Test Prod Csg |
| 3) Remove WH & Install BOP | 16) Run Cement Bond Log |
| 4) Release Pkr & POOH w/Tbg & Inspect | 17) Retrieve BP & Lay Down Workstring |
| 5) RU WL & Run Gauge Ring & Junk Bskt | 18) Test In-Hole w/Seal Assembly & Prod Tbg |
| 6) RIH w/Baker Mod D Pkr w/Plug | 19) Fill Annulus w/Pkr Fluid |
| 7) Run Cement Bond Log and tag TOC | 20) Swab Well to Equalize |
| 8) Run BP & Set Below TOC | 21) RU WL & Fish Plug from Pkr |
| 9) Run Perf Gun & Perf Prod Csg | 22) Flow Well to Clean-up |
| 10) Run Prod Pkr & Set above Perfs | 23) Return Well to Service |
| 11) Pump Cement & Circ to Surface | |
| 12) Wait on Cement | |
| 13) Retrieve Prod Pkr & Lay Down Work String | |

14. I hereby certify that the foregoing is true and correct

Signed David L. Brewster

Title Reservoir Engineer

Date 3/13/92

(This space for Federal or State official use)

Approved by

Title

Date

3/25/92

Comments of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations or to any officer within its jurisdiction.