,	r.		15
Fo:m 3i60-5 (June 1990)	DEPARTMENT	D STATES OF THE INTERIOR ND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals  SUBMIT IN TRIPLICATE  Type of Well  Gas Use Submit and Submit			5. Lease Designation and Serial No. <u>LC 068431</u> 6. If Indian, Allottee or Tribe Name Dir.
			7. If Unit or CA, Agreement Designation
			Poker Lake
2. Name of Operator			8. Well Name and No.
BASS ENTERPRISES PRODUCTION COMPANY 3. Address and Telephone No.			Poker Lake Unit #41 9. API Well No.
P. 0. Box 2760, 4. Location of Well (Forman 6	Midland, Texas	79702 (915) 683-2277	
<ul> <li>4. Location of Well (Footage, Sec., T., R., M., or Survey Description)</li> <li>1980' FNL &amp; 1980' FEL of Section 21, T24S, R30E Unit Letter G</li> </ul>			10. Field and Pool, or Exploratory Area Dog Town Draw 11. County or Parish, State
			Eddy County, New Mexi
TYPE OF SUBM	AUPHIATE BOX(s) T	O INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA
X Notice of Intent		TYPE OF ACTIO	N
Subsequent Repo	ļ	Abandonment Recompletion	Change of Plans
Final Abandonme	nent Notice	Plugging Back Casing Repair Altering Casing	Won-Routine Fracturing Water Shut-Off
		Other	Conversion to Injection
Describe Proposed or Completed C	Operations (Clearly state all pertine	ne danil.	Dispose Water (Note: Report results of multiple completion on Well
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> </ul>	000'. Cap with 3 -7593'	ent details, and give pertinent dates, including estimated date of starti is for all markers and zones pertinent to this work.)* 5' Class H cement.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> </ul>	000'. Cap with 3 -7593'. gals 30# crossi	ent details, and give pertiment dates, including estimated date of starti as for all markers and zones pertiment to this work.)* 5' Class H cement. nked gel + 10,000# sand.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> <li>Frac with 2600</li> </ul>	000'. Cap with 3 -7593'. gals 30# crossi	5' Class H cement.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> <li>Frac with 2600</li> </ul>	000'. Cap with 3 -7593'. gals 30# crossi	5' Class H cement.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> <li>Frac with 2600</li> </ul>	000'. Cap with 3 -7593'. gals 30# crossi	5' Class H cement.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
. Set CIBP @ 11,0 . Perforate 7583- . Frac with 2600 . Install product	000'. Cap with 3 -7593'. gals 30# crossli tion equipment.	5' Class H cement.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> <li>Frac with 2600</li> </ul>	000'. Cap with 3 -7593'. gals 30# crossli tion equipment.	5' Class H cement. nked gel + 10,000# sand. Greg Spencer	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> <li>Frac with 2600</li> <li>Install product</li> <li>Install product</li> </ul>	000'. Cap with 3 -7593'. gals 30# crossli tion equipment.	5' Class H cement. nked gel + 10,000# sand. Greg Spencer TiueProduction Engineer	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> <li>Frac with 2600</li> <li>Install product</li> <li>Install product</li> </ul>	000'. Cap with 3 -7593'. gals 30# crossli tion equipment.	5' Class H cement. nked gel + 10,000# sand. Greg Spencer	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled
<ul> <li>Set CIBP @ 11,0</li> <li>Perforate 7583-</li> <li>Frac with 2600</li> <li>Install product</li> <li>Install product</li> </ul>	000'. Cap with 3 -7593'. gals 30# crossli tion equipment.	5' Class H cement. nked gel + 10,000# sand. Greg Spencer Tiue Production Engineer	(Nore: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled.