Form 9-331 (May 1963)	UNTED STATES SUBMIT IN TRIPL OF THE INTERIOR verse side	re- J. LEASE DESIGNATION AND SERIAL NO.
		NM-0459053
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use	UNDRY NOTICES AND REPORTS ON WELLS this form for proposals to drill or to deepen or plug back to a different reservol Use "APPLICATION FOR PERMIT—" for such proposals.)	ir.
(Do not use	Use "APPLICATION FOR PERMIT—" for such proposals.)	7. UNIT AGREEMENT NAME
1.		1. UNIT AGREEMENT NAME
	ELL OTHER	S. FARM OR LEASE NAME
2. NAME OF OPERAT	OR A	
Hanson Oi	L Corporation V	Red Bluff Federal
3. ADDRESS OF OPE		
P. O. Box 4. LOCATION OF WE See also space 1	1515, Roswell, New Mexico 88201, E E E I V	ED 10. FIELD AND FOOL, OR WILDCAT
At surface	-	T 11. SEC., T., R., M., OR BLK. AND
	JUL 2 9 197	SURVEY OR AREA
1980' FE	L and 1980' FNL	Sec. 27, T 26S, R 29E
	0. C. C.	12. COUNTY OR PARISH 13. STATE
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, CR. PEBIA, DFFIC	Eddy New Mexico
216-05	-21014 2876'G.L.	Ludy New Hexico
16.	Check Appropriate Box To Indicate Nature of Notice, Rep	ort, or Other Data
10.		SUBSEQUENT REPORT OF:
	NOTICE OF INTENTION TO:	
TEST WATER S	HUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TRE.	AT MULTIPLE COMPLETE FRACTURE TREATM	
SHOOT OR ACIE	IZE ABANDON* SHOOTING OR ACID	ABANDONMENT*
REPAIR WELL	CHANGE PLANS (Other)	ort results of multiple completion on Well
(Other)	Completion of Co	or Recompletion Report and Log form.)
17. DESCRIBE PROPO proposed wo nent to this y	SED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinerk. If well is directionally drilled, give subsurface locations and measured and twork.) $*$	rue vertical depths for all markers and zones pert
5-20-77	POOH w/tbg., ran CIBP set @ 2875', circ. hole cement from 2875' - 2825', lay down tbg. Shut	w/mud, spotted 4 sx. cement, in overnight.
5-21-77	Rig up hydraulic jack, shot csg. @ 2779' and 2 Range 3 5 1/2" 14# J-55 csg.	290', lay down 57 joints (2290
5-24-77	Ran tbg. to 2348', spotted 30 sx. cement. Pull cement, POH to spot 10 sx. plug @ surface. Rig	tbg. to 400', spotted 40 sx. ; down.
	Install dry hole marker.	
<i>,</i> *	Removed all equipment and debris, leveled loca	ition and pits.
		RECEIVED
		JUN 17 1977
	ر ا^{لار}ت ا	H J OON I . I.
	Control of the second sec	H JUS. GEOLOGICAL SURVEY
		ARTESIA, NEW MEXICO
	1 2	01
18. I hereby certi	ty that the foregoing is true and correct	
	Title Vice-President Pr	coduction DATE June 16, 1977
SIGNED		
(This space f	or Federal or State office use)	···
	TITLE	DATE
APPROVED I CONDITIONS	OF APPROVAL, IF ANY:	· · · · · · · · · · · · · · · · · · ·
TODIN	1 g	
10000	*See Instructions on Reverse Side	
1. 2.8		
Jul A.	brit	
x 1 pu	in the second	
/ R L		

ومحدثه والمر