CORRAL DRAW UT #1

9.0-83-22.0. (11) 1597 ND sh, 172 hole, NND, 1/11 WO driving tool 31 hrs, drove DP loose in 1 hr, POH w/ DP, corrected top of fish 0 661, mixed mud, loaded hole, ran 17½ bit on 5-9/16 DP to 431, CO to top of fish 661, started loosing mud, pull bit to 300, mixed mud, ran bit 570', started loosing mud, pull bit to 300, mixing & cond mud past 5 hrs.

CORRAL DRAW UT #1

- 10.1-38-9.0. (12) 1597 ND sh, 17½ hole, NND, 1/12 ran bit to 661, top of fish, lost circ, pull bit to 300, mixed mud & LCM, rerun bit to 631, CO to 661, top of fish, circ hole clean, POH, ran 16" OD WO mill on 4 jts 11-3/4 and 5 jts 10-3/4 WP to 661, now WO fish @ 721, 60' over fish w/ full circ.
- 9.8-47-6.0, 10% oil. (13) 1597 ND sh, 17½ hole, NND, 1/13 WO fish 721-738/3 hrs, twisted pin off kelly, ran OS, caught fish, POH, LD 16" WO mill, prep to run 124 WO mill, down 7 hrs on light plant, WO kelly jt.
- 9.8-46-6.0, 10% oil. (14) 1597 ND sh, 17¹/₂ hole, NND, 1/14 WO kelly 3 hrs, ran 12½ WO mill, WO DP from 730-937/9 hrs circ clean, POH, ran DP, screwed into fish @ 661, POH, rec 1 jt 5-9/16 DP, tool jt and piece of DP 14" long swelled by string shot, prep to run OS w/ mill, top of fish @ 693.

CORRAL DRAW UT #1

9.8-48-6.0, 8% oil. (15) 1597 ND sh, 17½ hole, NND, 1/15 ran 11-3/4 x 5½ mill on 3 - 7½ DC's, BS, jars, 5-9/16 DP, milled over top of fish 693-697, POH, ran OS on fishing tools to 693, caught fish, jarred & worked fish up hole 72' in 9 hrs, fish stuck, unable to move, Homco ran sinker bars in fish, stopped @ 971, ran free pt indicator, BO 5-9/16 DP @ 965, now POH, bottom of fish 1503, top @ 965, prep to run DP, screw into fish and CO inside.

CORRAL DRAW UT #1

9.8-47-6.0. (16) 1597 ND sh, 175 hole, NND, 1/16 Finish POH, rec 10 jts 5-9/16 DP, ran DP to 965, ran Homco 212' 14 CO pipe, pumped CO pipe out of rope socket, POH w/ DP, rec CO pipe, rerun DP, CO w/ CO pipe and spud bars to 1292, ran free pt indicator, indicated DC's stuck @ 1118, BO @ 1114, now POH w/ fish.

CORRAL DRAW UT #1

9.8-40-6.0. (17) 1597 ND sh, 17½ hole, 1/17 finish POH, rec 3 jts 5-9/16 DP & 2 - 7½ DC's, ran 17½ bit on 5 - 7¹/₂ DC's and DP, CO from 661-1114, top of fish, cond mud & circ 14 hrs, POH, ran 124 WO mill on WP, jars, DC's & DP to 1114, prep to WO fish, down 3 hrs cleaning pits and mixing mud.