

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

OCT 14 1991

WELL API NO. 30-015-21-81
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. IG-9681
7. Lease Name or Unit Agreement Name CHELSI
8. Well No. 1
9. Pool name or Wildcat Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR ABANDONMENT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator H. E. LEE ✓
3. Address of Operator 1306 Meadow Lane Roswell, New Mexico 88201
4. Well Location Unit Letter <u>J</u> : <u>1980'</u> Feet From The <u>South</u> Line and <u>1980'</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>26 South</u> Range <u>25 East</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Continuous Operations</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-16-91 thru 9-24-91

Drill cement and clean out hole from 462' to 485' and fall free.

9-25-91 thru 9-30-91

Clean out hole from 485' down to 504'. Drill out old cross-tie and junk.

10-1-91 thru 10-10-91

Drill on junk and recover more pieces of wood, paper sacks, wire, and tag more cement at 515'. Drill cement to 520'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. E. Gene Lee TITLE Owner DATE 10-11-91

TYPE OR PRINT NAME H. E. Gene Lee TELEPHONE NO. 622-7355

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE OCT 24 1991

CONDITIONS OF APPROVAL, IF ANY: