

- 4/1 CORRAL DRAW UT #2
(106) 12,300, prep to drill sh 6-1/2 hole. 15.6-48-12.0.
Finish POH w/magnetic basket, rec 1 cone in 3 pieces,
reran basket to 12,300, circ 4 hrs, POH, rec 1/2 cone &
3 pieces, ran bit #5 HTC J33 prep to drill.
- 4/2 CORRAL DRAW UT #2
(107) 12,364 drlg sh, 6-1/2 hole, NND. 15.5-49-11.0.
- 4/3 CORRAL DRAW UT #2
(108) 12,412 drlg sh, 6-1/2 hole, NND. 15.4-49-11.0.
- 4/4 CORRAL DRAW UT #2
(109) 12,445 drlg sh, 6-1/2 hole, NND. 15.5-49-11.0.
- 4/5 CORRAL DRAW UT #2
(110) 12,450 drlg sh, 6½ hole, 15.6-50-11.0.
3° @ 12,440, finish POH w/ bit #5, left 1/2 of cone in
hole, ran 5-3/4 magnetic bskt on DC's & DP to 12,445,
ci5c 3 hrs, POH, rec 1/2 cone, ran bit #6.
- 4/7 (112) 12,530 drlg sh, 6½ hole, NND. 15.6-50-11.0.
- 4/8 CORRAL DRAW UT #2
(113) 12,582 drlg lm & sh, 6½ hole, NND. 15.6-50-11.0.
- 4/9 CORRAL DRAW UT #2
(114) 12,611 drlg lm & sh, 6½ hole, 15.6-50-11.0.
3° @ 12,575.
- 4/10 CORRAL DRAW UT #2
(115) 12,658 drlg lm & sh, 6½ hole, NND. 15.5-56-11.0.
- 4/11 CORRAL DRAW UT #2
(116) 12,720 drlg lm & sh, 6½ hole, NND. 15.4-63-11.0.
- 4/12 CORRAL DRAW UT #2
(117) 12,770 drlg lm & sh, 6½ hole, NND. 15.6-61-11.0.
- 4/13 (118) 12,787 ND lm & sh, 6½ hole, NND. 15.5-53-8.8.
lost 100% circ @ 12,787, pull bit to 10,950, mixing mud,
attempting to regain circ past 14 hrs.
- 4/14 (119) 12,787 ND lm & sh, 6½ hole, NND, 15.2-15.6-50-12.4.
pull bit to 8650, mixed mud 4½ hrs, had 10% circ, POH, ran
HTC bit J55, broke circ @ 4140 & 7000, now circ @ 9850, full
circ, prep to run bit to bottom.
- 4/15 CORRAL DRAW UT #2
(120) 12,823 drlg lm & sh, 6½ hole, 15.4-46-11.4.
circ 2 addl hrs @ 9850, ran bit to 11,527, circ off gas
3½ hrs, ran bit to bottom, down 3 hrs for rprs.
- 4/16 CORRAL DRAW UT #2
(121) 12,893 drlg lm & sh, 6½ hole, NND. 15.4-45-11.4.
- 4/17 CORRAL DRAW UT #2
(122) 12,924 ND lm, 6½ hole, NND. 15.3-44-11.0.
had drlg break from 12,910-12,916, lost circ @ 12,924,
mixed mud & LCM, now circ thru ck manifolds w/ full circ,
prep to drill.