

- 3/13 CORRAL DRAW UT #2
(87) 11,652 ND, CO @ 11,572, 6-3/4 hole, 15.8-49-7.0.
raised mud wt to 15.8#, ran bit to 10,980, circ 3 hrs,
ran bit & tag fillup @ 11,562, now CO @ 11,572.
- 3/14 CORRAL DRAW UT #2
(88) 11,680 drlg lm & sh, 6-3/4 hole, NND, 15.6-55-8.8.
finish CO to 11,652, lost 80 bbls mud, mixed LCM & cond
mud & pumped off gas 10 1/4 hrs.
- 3/15 CORRAL DRAW UT #2
(89) 11,704 drlg lm & sh, 6-3/4 hole, 15.6-57-7.8.
5° @ 11,700, broke circ @ 5000, 7500 & 10,000, prep to
run bit to bottom.
- 3/16 (90) 11,731 drlg lm & sh, 6 1/2 hole, NND, 15.6-50-10.0.
ran bit to 10,273, circ off gas & cond mud 6 hrs, ran
bit to 11,704, circ off gas & cond mud 6 1/4 hrs.
- 3/17 (91) 11,775 drlg lm & sh, 6 1/2 hole, NND. 15.6-55-8.8.
- 3/18 CORRAL DRAW UT #2
(92) 11,820 drlg sh, 6 1/2 hole, NND. 15.6-55-8.6.
- 3/19 CORRAL DRAW UT #2
(93) 11,860 drlg lm & sh, 6 1/2 hole, NND. 15.6-54-8.0.
- 3/20 CORRAL DRAW UT #2
(94) 11,912 drlg lm & sh, 6 1/2 hole, NND. 15.5-51-9.2.
- 3/21 CORRAL DRAW UT #2
(95) 11,960 drlg lm & sh, 6 1/2 hole, NND. 15.6-51-9.2.
- 3/22 CORRAL DRAW UT #2
(96) 11,987 drlg lm & sh, 6-1/2 hole, 4° 11,955. 15.6-54-10.0.
Broke circulation 3 times while making trip, pumped off
gas 3 hrs @ 11,960.
- 3/24 (98) 12,073 drlg lm & sh, 6-1/2 hole, NND. 15.7-51-9.6.
Down 5-3/4 hrs cleaning pits & repairs.
- 3/25 CORRAL DRAW UT #2
(99) 12,116 drlg lm & sh, 6-1/2 hole, NND. 15.6-48-8.4.
- 3/26 CORRAL DRAW UT #2
(100) 12,148 drlg lm & sh, 6-1/2 hole, NND. 15.6-54-9.6.
- 3/27 CORRAL DRAW UT #2
(101) 12,182 drlg lm & sh, 6-1/2 hole, NND. 15.6-46-8.8.
- 3/28 CORRAL DRAW UT #2
(102) 12,226 drlg lm & sh, 6-1/2 hole, NND. 15.7-51-9.
- 3/29 (103) 12,274 drlg lm & sh, 6-1/2 hole, NND. 15.5-47-10.4.
314/168 hrs.
- 3/31 (105) 12,300 ND lm & sh, 6-1/2 hole, 3-1/4° @ 12,255. 15.6-50-10.
POH w/bit #4, left cones off bit in hole, ran 5-1/2"
magnetic basket to 12,230, CO to 12,300, circ gas off
3 hrs POH, rec 1-1/2 cones ran basket to 12,260 CO to
12,300, circ gas off 3 hrs now CH.