

RECEIVED BY BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

NAME **AMESIA OFFICE**

Mobil Producing TX & NM Inc. ✓

3. ADDRESS OF OPERATOR

9 Greenway Plaza - Suite 2700 - Houston, TX 77046

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1980' FWL & 1580' FSL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3062 GL; 3078 KB

5. LEASE DESIGNATION AND SERIAL NO. **cl**
NM-14778

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Section 22 Federal

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Corral Draw (Undesignated)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit K. Sec. 22, T25-S, R29

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Plug back

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6-27-84 MIRU Monument Well Serv DD Unit.

6-29-84 Chem cut 2-7/8 tbg @ 11,335, POH w/ prod tbg.

6-30/7-1-84 Set 5-1/2 CIBP @ 11,335, JC, WIH w/open end 2-7/8 tbg to 11,330, Circ hole w/500 bbl 10# Br wtr. John Wade w/BLM, Carlsbad, NM notified of intentions of changing plugging procedure w/c zone, ok'd, job not witnessed.

7-2-84 SD bad weather.

7-3/4-84 Spot 95x (126 cu. ft.) Cl H cmt 11,335-10,710, spot 10# mud 10,710-9900, spot 35x (46 cu. ft.) Cl H 9900-9800, Displ csg w/430 bbl 2% KCL fr wtr, JC, POH w/2-7/8 tbg, set 7-5/8 CIBP @ 9800 PBTD. Notified Mr. Cope w/BLM on 7-2-84. Job not witnessed.

7-5-84 Ran logs.

7-6/10-84 WO perfs.

7-11-84 Perf 7-5/8 csg w/4 sqz holes @ 7850, JC, set 7-5/8 cmt ret @ 7850.

7-12-84 Press 7-5/8 csg annulus to 1500 psi. HOWCO cmt'd thru sqz holes @ 7580 w/625x (1131 cu. ft.) TLW + 300x (397 cu. ft.) Cl H Neat. Final press = 1000 psi, pulled out of ret, rev out 5x cmt @ 7790, TOC @ 7790, JC, POH w/2-7/8 tbg & stinger.

(SEE ATTACHED)

18. I hereby certify that the foregoing is true and correct

SIGNED

Nancy Lewis

TITLE

Authorized Agent

DATE

5-16-85

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAY 31 1985

*See Instructions on Reverse Side