

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPI
(Other instructions
verse side)

TE*
re

Form Approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER dry		7. UNIT AGREEMENT NAME Ross Draw
2. NAME OF OPERATOR Penroc Oil Corporation		8. FARM OR LEASE NAME Ross Draw Unit
3. ADDRESS OF OPERATOR P. O. Drawer 831, Midland, Texas 79702		9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27-26S-30E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 2995.5 GR		12. COUNTY OR PARISH Eddy
		13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input checked="" type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/18 to 7/23/77:

Shot 9 5/8", 47#, N-80 casing off @ 6482'. Pulled and recovered 162 joints (6482').

7/25/77:

Verbal approval by Jim Knauf to set cement plugs.

1. Set 150' cement plug (Class H cement) 6556-6406' across stub-end of 9 5/8" casing.
2. Set 150' cement plug (Class H cement) 5056-4906'.
3. Set 100' cement plug (Class H cement) 3349-3249' in and out of 13 3/8" casing set @ 3300'.
4. Spot 20' cement plug in top of 13 3/8" casing.

RECEIVED

AUG 9 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED George J. Dalling

TITLE President

DATE 8/8/77

(This space for Federal or State office use)

APPROVED BY Joe L. Lara

TITLE ACTING DISTRICT ENGINEER

DATE DEC 12 1977

CONDITIONS OF APPROVAL, IF ANY: