9. WELLSITE LAYOUT:

A. Please refer to Exhibit C on which is shown a configuration of WEK rig layout. The well site falls from east to west and will require about 4' cut and fill. We do not plan to line reserve pits.

10. PLANS FOR RESTORATION OF THE SURFACE:

A. If the well is completed as a producing well, we will knock down pits and smooth out the surface. If not productive, in addition to the above, we will level the location.

11. OTHER INFORMATION:

- A. There is a grazing lease owner and his name is W. M. Snyder. We will contact him and work out an agreement.
- B. There is a cattle guard and gate on existing lease road. There are no ponds, lakes, streams or rivers in the area.
- C. There is no evidence of any archaeological, historical or cultural sites in the area.
- D. There are no occupied dwellings in the immediate area. A windmill is located in Section 4.
- E. Topography consists of sand dunes with mesquite, broomweed and shinnery. Usual wildlife for this area includes jackrabbits, reptiles, etc.

12. OPERATOR'S REPRESENTATIVES:

A. The field representatives responsible for assuring compliance with the approved surface use and operations plan are:

Peck Hardee	Fred G. Yates
Harvey E. Yates Company	Harvey E. Yates Company
Suite 300	Suite 300
Security National Bank Bldg.	Security National Bank Bldg.
Roswell, New Mexico 88201	Roswell, New Mexico 88201
Mobile: 505/623-0989 #4114	Mobile: 505/623-0989 #4109
Office: 505/623-6601	Office: 505/623-6601
Home: 505/623-8980	Home: 505/622-5387