

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

SEP 27 '88

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ SWD Well

2. NAME OF OPERATOR CRW-SWD, Inc. ✓

3. ADDRESS OF OPERATOR O. C. D. ARTESIA OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
805 One First City Center, Midland, Texas 79701
910' FNL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.
NM 0554774 (ROW NM67324)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
ROSS DRAW UNIT

8. FARM OR LEASE NAME
ROSS DRAW UNIT

9. WELL NO.
9

10. FIELD AND POOL, OR WILDCAT
ROSS DRAW
Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 34
T. 26 S., R. 30 E.

12. COUNTY OR PARISH
Eddy

13. STATE
N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☒
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8-8-88 RU Penwood W/L. Shot Delaware zone from 4422-4632 w/109 holes of 0.41" diam. in 6 runs w/casing gun. All shots fired. Holes perfered in 2% KCl. Holes shot were: 4422,23,24,25,26,27,28,29,30,33,34,35,36,37,38,39,40,41,42,43,44,45,46,51,52,53,55,56,57,76,77,78,79,80,81,82,83,84,85,86,87,88,89,90,91,92,93,94,95,96,97,98,99,4500,01,02,03,04,05,06,4582,84,85,86,87,88,89,90,91,92,93,94,95,96,87,98,99,4600,01,02,03,04,05,06,07,08,09,10,11,13,14,15,16,17,18,19,20,21,22,23,24,25,26,27,28,29,30,31,32. Good Job.

8-9-88 Prep to acidize Delaware zone from 4422-4632. End of tbg. @ 4632 w/2 jts. tbg. below packer, spotted 8 bbls acid across perfs. LD 8 jts. End of tbg. @ 4389'. Set packer @ 4328' w/14 pts. wt. Tested casing to 500#-held ok. Acidized Delaware zone w/12,000 gals. 7 1/2% NEFE. Formation broke @ 400# after no time. Used 1.3 balls. Dropped 10 balls every 10 bbls. Flushed w/2% KCl. Total load 302 bbls. Total recovery-300 bbls.

FILE

18. I hereby certify that the foregoing is true and correct

SIGNED Kala Schmidt

TITLE Agent

DATE 8-29-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side