

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☐ well other ☒ Dry
2. NAME OF OPERATOR
Amoco Production Company
3. ADDRESS OF OPERATOR
P. O. Box 68 Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL & 660' FEL, Sec. 26
AT TOP PROD. INTERVAL: (Unit I, NE/4, NE/4)
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: | | SUBSEQUENT REPORT OF: | |
|--------------------------|--------------------------|-----------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | | <input checked="" type="checkbox"/> |
| (other) | | | |

5. LEASE
NM-22625
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Federal BQ
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Wildcat Morrow
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
26-26-25
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
30-015-23442
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3636.3' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged well per the following:

Set a 200' (85-sack) Class H cement plug 10130'-10330'.
Set a 150' (65-sack) Class H cement plug 9075-9225'.
Set a 150' (65-sack) Class H cement plug 7705-7855'.
Set a 150' (65-sack) Class H cement plug 6025-6175'.
Set a 100' (65-sack) Class H cement plug 4977-5077'.
Set a 20' Class H cement surface plug and installed P X A marker.
Location is ready for inspection.

0+4-USGS, A 1-Hou 1-Susp 1-LBG 1-W. Stafford, Hou 1-Getty 1-Hudson
X Hudson

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Benton Green TITLE Ast. Adm. Analyst DATE 1-13-81

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER TITLE ACTING DISTRICT ENGINEER DATE JAN 15 1981
CONDITIONS OF APPROVAL, IF ANY: