

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

5. LEASE

NM-16085

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Meander Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 11, T25S, R25E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

NA

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3460' GR

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR

The Superior Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 3901, Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660' FEL, 1980' FSL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Bone Spring Completion Attempts

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-25-83 MI WO rig, set blanking plug in "F" nipple @ 10,894'. Loaded tbg w/40 bbls 2% FWKCI, tested plug to 1000 PSI - OK.

8-26-83 NU BOP, unset from pkr, POH w/tbg.

8-27-83 Capped Baker "DB" pkr @ 10,880' w/48' cmt, WOC 2 hrs, tested 500 PSI-OK. Set CIBP @ 8400', capped w/38' cmt - new PBTD is 8362'. Tested plug and csg to 3000 PSI - OK.

8-28-83 Ran CBL, log indicated good cmt bond to 4800' approx.

(Over)

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED G. E. Tate TITLE Div. Opr. Supt. DATE June 21, 1983

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

AUG 29 1983

ROSWELL, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

CPO : 1981 0 - 347-166

8-29-82	Spotted 300 gals 7 1/2% HCl acid + additives, perf'd 6682-6689'; 6692-6695'; 6698-6709' w/2 1/2" JSPF. (Total 48 holes).
8-30-82	No report.
8-31-82	Ppd 3000 gals 7 1/2% HCL + additives, dropped 7 1/2 - 7/8" RCNB's, swabbed.
9-1-82	Swabbed, open to test tank.
9-2-82	Swabbed.
9-3-82	Swabbed.
9-4-82	Swabbed dry, closed well in. Operations Suspended.
9-11-82	CITP 925 PSI after 235 hrs SI time.
9-12-82	RU Cudd Coil tbq unit, jetted well - no oil or wtr recovery. Suspended Operations. Will P&A.