

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

| |
|--|
| 1. oil well <input type="checkbox"/> gas well <input checked="" type="checkbox"/> other |
| 2. NAME OF OPERATOR THE SUPERIOR OIL COMPANY |
| 3. ADDRESS OF OPERATOR P. O. BOX 4500 THE WOODLANDS, TEX. 77380 |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1980' FNL & 1980' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA |

| | |
|---|-------------------------|
| 5. LEASE NM - 18042 | |
| 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | |
| 7. UNIT AGREEMENT NAME | |
| 8. FARM OR LEASE NAME SOTOL FEDERAL | |
| 9. WELL NO. 1 | |
| 10. FIELD OR WILDCAT NAME WILDCAT | |
| 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12, T 24S, R 31E | |
| 12. COUNTY OR PARISH EDDY | 13. STATE NEW MEXICO |
| 14. API NO. | |
| 15. ELEVATIONS (SHOW DF, KDB, AND WD) GL 3526' KB 3557.5' | |

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

| |
|-------------------------------------|
| <input type="checkbox"/> |
| <input type="checkbox"/> |
| <input checked="" type="checkbox"/> |
| <input type="checkbox"/> |
| <input type="checkbox"/> |
| <input type="checkbox"/> |
| <input type="checkbox"/> |
| <input type="checkbox"/> |

RECEIVED

APR 10 1981

O. C. D.
ARTESIA, OFFICE

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Cleaned out hole.
2. Circ. hole w/10# Brine and WT 1270
3. Ran GR/CCL/CBL/VDL from 15,299'-13,200'.
4. Set Baker FA-1 packer @ 14,700'
5. Perforated 14,988'-14,996', 15,000'-15,010, 15,017'-15,025', 15,036'-15,046' and 15,049'-15,058'.
6. Acidized w/8000 gals 7 1/2% HCl and 2000 SCF N₂/BBL
7. Swabbed and Tested.
8. Fraced w/67,500# sand and 48,000 gals gell water @ 13 BPM @ 8400 psi.
9. Jetted and Tested.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED L.H. BOHOT L.H. BOHOT TITLE ENGR. SUPERVISOR DATE 4/1/81

| | |
|--|---|
| APPROVED BY PETER W. CHESTER TITLE _____ DATE _____ | ACCEPTED FOR RECORD (This space for Federal or State office use) APR 8 1981 U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO See instructions on Reverse Side |
|--|---|

CC: USGS (4), EAR, PFP, PRB, JWH, RG, GLS, RMB, BJW, CF, RES

RECEIVED

APR - 6 1981

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO