Form 9-321 (May 1963)

16.

6/26/82

RD WSU.

TED STATES U LED STATES SUBMIT IN TR (Other Instructio. DEPARTMENT OF THE INTERIOR verse side)

CATE.

Form approved.

<u> </u>		Budget	Burea	u N	o. 42-R	142
j,	LEASE	DESIGN	ATION	AND	SERIAL	NO.

on	re-							
	- 1	5.	LEASE	DESIG	NATION	AND	SERIAL	NO
	- 1	ı						

	GEOLOGICAL SURVEY	N Mex. 35607
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use "APPLICATION FOR FERMIT-" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	OIL GAS X OTHER	7. UNIT AGREEMENT NAME
2.	NAME OF OPERATOR	8. FARM OR LEASE NAME
3.	Ike Lovelady, Inc.	Ross Draw Fed. Comm.
4.	P.O. Drawer 2666; Midland, Texas 79712 1/5. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface.	10. FIELD AND POOL, OR WILDCAT
	00T 22 532 660' FNL & 1980' FWL of Sec. 33	Wildcat 11. SEC, T., E., M., OR BLK. AND SURVEY OR AREA Sec. 33, T-26-S, R-30-E
14	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) A. O. F. E.	12. COUNTY OR PARISH 13. STATE
		Eddy N. Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

The state of the s			SUBSEQUENT REPORT OF:		
Γ				لـــــــا	
TEST WATER SHUT-OFF	- PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL	CHANGE PLANS		(Other)		
(Other)			(Note: Report results of m Completion or Recompletion	altiple completion on Well Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6/11/82	Cir. & Mix mud, Prep. to retrieve RBP & Rtts.
6/12/82	Could not wash down to RBP W/Rtts in hole, POH W/Rtts, PU BHA & RBP
	retrieving tool. TIH W/2-7/8" Tbg. Retrieve RBP. POH L.D. RBP.
6/13/82	PU 5-3/4"X2-7/8" O.S. & TIH W/BHA & 2-7/8" Tbg. Latch onto fish, could
	not pull. R.U. WL Trk. RIH to 12,247', W.L. parted @ Pack-off.
6/14/82	PU 1-5/8 D.P. TIH W/centre spere & fish W.L., RU WL Trk, & run
	free point. Fish Free POH.
6/23/82	PU 7-5/8" 38# Baker Lock Set Pkr. RIH W/2-7/8" Tbg. Displace hole
	W/10# brine. Set Pkr.

18. I hereby certify hat the foregoing is true and correct TITLE Manager of Production SIGNED (This space for (ORIG. SGD.) APPROVED BY CONDITIONS OF APPROVOCT 2N 1982

U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXIC *See Instructions on Reverse Side