Submit 3 Copies

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 RECEIVED Santa Fe, New Mexico 87504-2088 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 APR - 6 1992 STATE FEE 🔲 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. O. C. D. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: State MA Com WELL WELL X OTHER 2. Name of Operator 8. Well No. MW Petroleum Corporation 9. Pool name or Wildcat 3. Address of Operator 1500 CityWest Blvd., Ste. 400, Houston, Tx 77042 Willow Creek (Bone Springs) 4. Well Location Feet From The AST # : 1980 Feet From The <u>*1.00 =</u> Line and NMPM_Eddy 25S County Section Range Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. **TEMPORARILY ABANDON CHANGE PLANS** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Recomplete to Willow Creek OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. State MA #1 1-23-92 MIRU WO rig. Pulled tbg & pkr. Set 25 sx cmt. Plug @ 11,349'-460'. Set 25 sx cmt. plug @ 9489'-600'. Set 50 sx cmt. plug @ 8920'-9060'. Set CIBP @ 8190'. Dumped 50 sx xmt. Set CIBP to 1000#. Perf'd intervals 7287'-306', 7310'-17', and 7405'-18'. TIH w/pkr & tbg. Set pkr. @ 7162'. Acidized w/4000 gal 15% HCL. RU SU. Swb back load. TIH w/press bombs. POOH w/press bombs. Flwd well to tank. Prepare to install lift equip. 2-19-92: Last date of operations. SIGNATURE TELEPHONE NO TYPE OR PRINT NAME ORIGINAL SIGNED BY (This space for State Use) MIKE WILLIAMS SUPERVISOR, DISTRICT IF APPROVED BY-