

2-16-82 Steve Douglas,
to set CIBP @ 6400 + copy 35'
cement. CIBP @ 6200 w/
35' cement. another one around
29.3000' setting Comp in Del,
to submit C-101 & C-102