COTTONWOOD SPRINGS FEDERAL COMM. #1 NE/4 Sec. 18, T25S, R26E EDDY COUNTY, NEW MEXICO

BRUSHY CANYON RECOMPLETION

COTTOINCOD SPRINGS FED. CON. #1



PROCEDURE

- 1. MOL and RU.
- 2. Load tubing and kill well with 10# brine.
- 3. Nipple down wellhead and NU BOP's (6" 1500 Series).
- 4. Sting out of Baker Retrieva-D Lok-Set packer at 11,250' and circulate hole with 10# brine.
- 5. TOH with 2 3/8" tubing. PU retrieving tool on 2 3/8" tubing and TIH. Release packer at 11,250' and TOH.