

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION
Drawer DD
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
FED NM 22207

6. If Indian, Allottee or Tribe Name
NA

7. If Unit or CA, Agreement Designation
Washington Ranch
Storage Area

8. Well Name and No.
WI No. 12

9. API Well No.
30-015-24036

10. Field and Pool, or Exploratory Area
Washington Ranch
Morrow

11. County or Parish, State
Eddy, NMX

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other Gas Storage

2. Name of Operator
El Paso Natural Gas Co. (J. W. Mulloy Assoc. - Agent)

3. Address and Telephone No.
1110 N. Big Spring Midland, TX 79701 (915-687-0323)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1045' FSL & 512' FEL Unit P
Sec 33 T-25-S R-24-E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5-03-94 MI equipment. Kill well w/9# brine. ND tree. NU BOP. POH w/tubing. RIH and set CIBP w/wireline @ 6710'. TIH. Spot 30 sx cmt on CIBP. Fill well w/9# mud. POH w/tbg. Cut 7" csg @ 4000' & POH. TIH w/tbg. Spot 40 sx cmt 4050'-3950'. WOC. TIH & tag cmt plug @ 3950' (Gene Hunt - BLM). Spot 60 sx cmt 3800'-3700'. Spot 60 sx cmt 850'-730'. WOC. Tag plug @ 730' (Mike Stubblefield - NMOCD). Spot 10 sx cmt 50'-surface. Cut off csg head. Install dry hole marker.

5-06-94 Move off well.

Part ID-2
7-15-94
P&A

14. I hereby certify that the foregoing is true and correct

Signed O. H. ROUTH Title AGENT Date 6-3-94

(This space for Federal or State office use)

Approved by ORIG. AGD Title PETROLEUM ENGINEER Date 6/30/94

Conditions of approval, if any: