

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NM OIL CONS. SUBMITTAL (Other Instructions on reverse side)
Alameda, NM 88210

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NM-105960 BY MAR-27 1987
2. NAME OF OPERATOR Jubilee Energy Corporation	7. UNIT AGREEMENT NAME O. C. D.
3. ADDRESS OF OPERATOR 4000 N. Big Spring, Suite 109, Midland, TX 79705	8. PART OF LEASE NAME ARTESIA OFFICE Hay Hollow Federal
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980' FEL of the Section	9. WELL NO. 1
14. PERMIT NO. N/A 30-015-24070	10. FIELD AND POOL, OR WILDCAT Wildcat - FS
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3170.9' KB, 3154.4' GL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T26S, R27E
	12. COUNTY OR PARISH Eddy
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Set CIBP @ 6100'. Spotted 35' cement with bailer.
2. Cut casing @ 2090'. Pulled casing.
3. Went in hole with tubing and spotted a 50' cement plug centered @ the cut. WOC 4 hrs.
4. Pulled tubing to 4500' and spotted a 100' cement plug from 4500' - 4600'. Pulled tubing to 3500', spotted cement plug from 3500' - 3600', pulled tubing to 2140', spotted cement from 2140' - 2240', tagged plug. Pulled tubing to 1150', spotted cement plug from 1150' - 1250'.
5. Pulled tubing to 505' and spotted a 100' cement plug centered @ the shoe, WOC 4 hrs., tagged plug.
6. Spotted 10 sx. cement in top of 8 5/8" casing and erected Plug and Abandon marker 8-9-85.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE 8-20-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

3-2887
Post ID-2
8-30-85
P4A