Frm 3160-5	
November 1983	ì
Formerly 0_31	

16

17

SIGNED

## UNITED STATES DEPARTMENT OF THE INTEDIOD

SUBMIT IN TRIPLICATE\*
(Other instructions on re-

Form approved. Budget Burgau No. 1004 Expires August 31, 1985

BUREAU OF LAND MANAGEMENT	5. LEASE DESIGNATION AND SERIAL N. NM 15302
SUNDRY NOTICES AND REPORTS CREWEUS  in not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.	6 IF INDIAN, ALLOTTEE OR TRIBE NAM
WELL WELL OTHER  2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME
Enron Oil & Gas Company 3. ADDRESS OF OPERATOR	8. FARM OR LEASE NAME Newyear Federal
P. O. Box 2267, Midland, Texas 79702  1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  See also space 17 below.)  At surface	9. WELL NO.  1 10. PIELD AND POOL, OR WILDCAT
2310' FSL & 990' FEL	Wildcat Delaware  11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR. etc.) 30. 015. 24389 2993 GR	Sec 3, T25S, R29E  12. COUNTY OF PARISH 13. STATE  Eddy NM
Check Appropriate Box To Indicate Nature of Notice, Report,	

No	TICE OF 1	NTENTION TO:	,	·		
TERM W				SUBSEQUENT	<b>REPORT OF:</b> 1/5/93	
TEST WATER SHUT-OFF	`   <u> </u>	PULL OR ALTER CASING		WATER SHUT-OFF		
FRACTURE TREAT	ii	MULTIPLE COMPLETE	-	i	BEPAIRING WELL	
SHOOT OR ACIDIZE	!	ABANDON*	***:	FRACTURE TREATMENT	ALTERING CASING	
REPAIR WELL		CHANGE PLANS	!:	SHOOTING OR ACIDIZING	ABANDON MENT*	<u>x</u>
(Other) DESCRIBE PROPOSED OR C				Other) NOTE: Report results of m Completion or Recompletion	ultiple completion on Well	

SCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TOH LD rods & pump; unseat packer; TOH with tubing & packer.

Load hole w/9# mud.

Set CIBP at 4975' and spot 35' cement plug from 4975' to 4940'.

Set CIBP at 3000' and spot 125' cement plug from 3000' to 2875'.

Shot 4-1/2" 10.5# casing at 1978'; TOH LD casing. - pump 100' cement plug across casing stub from 1978' to 1878' - tagged plug at 1939'.

Shot 8-5/8" 24# & 32# casing at 1285'; TOH LD casing. - Pump 60 sack plug at 1335' Tagged cement plug at 1220' Cement plug from 1220' to 1335' with casing stub at 1285'.

Spot 110 sack plug from 494' to 350' - Tagged cement at 330'.

Set 50 sack surface plug.

Rig released 1-14-93. P&A. Installed dry-hole marker.

Approved as to slugging of the well bore. Liability under bond is retained until surface restoration is completed.

TITLE Regulatory Analyst

(This space for F CONDITIONS OF APPROVAL.