

tel  
up

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

FEB 2 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER Workover  
2. Name of Operator  
YATES PETROLEUM CORPORATION  
3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location  
Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section 3 Township 26S Range 28E NMPM Eddy County  
10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
2937' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. NOTE: Work was being done over expiration date of February 1, 1993.  
Work was done 1-30-93 thru 2-3-93.  
1-30-93: Moved in and rigged up. Pulled pump and rods. Unset tubing anchor. POOH with tubing. WIH w/bit and scraper. Tagged up on junk at 3300'. Worked down hole to 6180'. POOH with bit and scraper. Rigged up reverse unit. WIH with bit and drill collars to 6180'. Tagged up. Cleaned out to 6235'. POOH. Laid down bit and collars. WIH w/casing guns and perforated 6039-6200' with 20 .45" holes as follows: 6039, 6042, 6044, 6068, 6071, 6077, 6080, 6084, 6122, 6123, 6155, 6157, 6160, 6169, 6173, 6180, 6186, 6188, 6195 and 6200'. RIH w/RBP and packer. Straddled perforations 6155-6200'. Treated with 1000 gallons 7-1/2% NEFE acid and 20 ball sealers. Communicated. Moved up hole with packer. Straddled perforations 6039-6200'. Treated with 1000 gallons 7-1/2% NEFE acid and 45 ball sealers.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Feb. 19, 1993  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE FEB 26 1993

CONDITIONS OF APPROVAL, IF ANY: