

Gulf Federal No. 2

Plug Back Procedure Continued:

4. TIH W/ 4-3/4" RB & 6 - 3-1/8" DC'S ON 2-7/8" TBG. TAG & DO CMT TO RET @ 4045'. TEST TOP SQZ HOLES TO 1000 PSI. TOH W/ TBG & TOOLS.
5. PERF CHERRY CANYON 3918-4024' W/ 4 SPF (425 HOLES) BY GEARHART COMP DENS/NEUTRON LOG DATED 9-26-84 CORRELATED TO CASED HOLE LOG PREVIOUSLY RUN. PERF USING A 4" HSC CSG GUN, 90° PHASING.
6. TIH W/ 5½" BAKER RDG PKR & SN TO 3900'. SWAB TEST CHERRY CANYON PERFS.
7. IF NECESSARY, RU WESTERN & ACDZ CHERRY CANYON W/ 1500 GAL 7-1/2% HCL @ 2 - 3 BPM, MAX PRESS 3000 PSI. FLUSH TO BTM PERF W/ 2% KCL WTR.
8. SWAB TEST CHERRY CANYON PERFS AS INSTRUCTED BY REGION OFFICE.
9. TOH & LD TBG & PKR. RR

FLUID DETAILS

BASE ACID	7-1/2% HCL
SURFACTANT	1 GPT NINE-40
INHIBITOR	1 GPT I-17A
CLAY STABILIZER	1 GPT CLAYMASTER 4
IRON CONTROL	15 PPT SODIUM ERYTHORBATE