Street, and a street of the st	U: ED STATES RTMENT OF THE INTER REAU OF LAND MANAGEME		Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DEBIGNATION AND BERIAL NO. NM 13997
SUNDRY N	OTICES AND REPORTS reportals to drill or to deepen or plu LICATION FOR PERMIT-" for such	ON WELLS g back to a different reservoir. a proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
ANELL CO. ONE DOTHI	ге.		7. UNIT AGREEMENT NAME
2. MANE OF DETEATOR	فن		8. FARM OR LEAGE NAME
I.C. Williamson			EP-USA
3. ADDRESS OF OPERATOR			9. WELL NO.
P.O. Box 16 Midland	1. Texas 79702		7
P. 0. Box 16 Midland, Texas 79702 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT Brushy Draw Delause
1980' FEL &1980' FSI	-	Wt. J	11. BEC. T. E. M. OB BLE. AND BURDET OR AREA SEC. 26 T-26-S, R-29-E
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, CR, etc.)	12. COUNTY OF PARISH 13. STATE
30-015-32032	2899.5 GR		Eddy NM
10. Check	Appropriate Box To Indicate	Nature of Notice, Report, or O	ther Data
NOTICE OF INTENTION TO :		BUBBEQUI	INT REPORT OF :
TEST WATER SHUT-OFF	PELL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTUBE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTEBING CABING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDON MENT
REPAIR WELL	CHANGE PLANS	(Other)	4-shard
(Other)		(Nors: Report results of Completion or Recomple	of multiple completion on Weil tion Report and Log form.)
17. DESCRIDE PROPOSED OR COMPLETED proposed work. If well is dir	OPERATIONS (Clearly state all pertine	ent details, and give pertinent dates, I	acluding estimated date of starting any

proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and tones pertinent to this work.) •

Pursuant to BLM instructions obtained January 6, 1985, the J.C. Williamson EP-USA #7 was plugged and aboandoned on January 7, 1985, and witnessed by a BLM representative.

Well was drilled to 472'. On 1-4-85 tried to run 13 3/8" surface casing, but wouldn't go. Went in hole to clean and ream. Bit stuck at 146'. Recovered all but one 30' x 6 1/8" drill collar and 17 1/2" bit. Top of fish at 112'. No casing in hole. Fill found at 70'. Set plug w/100sx Haliburton thickset. Set plug w/35 sx Class "C", 4% CaCl<sub>2</sub>, got 1' fill. Set 3rd plug w/50 sx same, got 1' fill; used 6 yards pea gravel, got 1' fill; 35 sx plug, go 8' fill. Filled hole w/12 yards pea gravel, got 1' fill, top of fill at 54'; hole now dry. Filled hole w/10 1/2 yards, 5 sx/yrd ready mix concrete; filled hole to top of celler. Placed metal plate in wet cement. Will install dry hole marker as soon as available, and when dry hole marker will not interfer w/future drilling operations.

Rig will be skid 20' to the south of the EP-USA #7. New well will be J.C. Williamson EP-USA #7-Y.

		• }	Pist FD-7-85
			and the second
18. I hereby certify that the foregoing is true and com SIGNED TOTAL	TITLE Agent		CEDIED FOR FOOD (
(This space for Federal or State office use)			R.P. 3 AS
CONDITIONS OF APPROVAL, IF ANY:			VJAN 24 199
	*See Instructions on Rev	verse Side	NEW IN CO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the