SELV STREED		- Lwer DD Artesia, NM	88210
BUREAU OF I	AND MANAGEMENT	UI 19 5 52 AM 194 NM 22634 NN WELLS reentry to a different reservoir.	
SUBMIT	IN TRIPLICATE	ECEIVED 1.	Y Unit or CA, Agronmer Donigo
West Oil Company		UG 22.94	Well News and No. Mobil '22' Feder Art Well No. 30-015-25105
5 <u>S. Sheridan Rd.</u> <u>Suit</u> Wed (Feering, Bee, T., R., M., <i>et Barray D</i> t I - 2310' FSL and . 22- 265-29E	warphill)	CONT WEDGE	Field and Feel, or Exploring A Brushy Draw - Do Commy or Pacific Sum Eddy, New Mexic
CHECK APPROPRIATE BOX	S) TO INDICATE NATURE OF	NOTICE, REPORT,	OR OTHER DATA
TYPE OF SUBMIBBION		TYPE OF ACTION	
KN Nation of Intent			Change of Flom
The Interspect Report	Phaging Book		Non-Bantiso Producing
	Cusing Seguir		Hear Sub-OF
Time Abustonment Nation	Abering Cosing		Convenies to Injector
		aling actionated data of standing sale	Dispose Water (Note: Report results of mobiles sampleti Comparises or Remorphism Perport and
This well changed to June 1, 1994. We plan to reactivate well, expanding current.		ned " status eff le future water ion project. udies, and shou	Dispess Wear New Superscription Complete Completes or Recompletion Report and propagated work. If well is direction ective injection

(Rev. 5/23/94)

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544 ; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,

3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.