

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI  
(Other instructions  
reverse side)

TE-  
re-

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

215F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> SWD		5. LEASE DESIGNATION AND SERIAL NO. NM-16814	
2. NAME OF OPERATOR Sun Exploration & Production Co.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 1861, Midland, Texas 79702		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter L, 660' FWL & 2055' FSL		8. FARM OR LEASE NAME Bedena Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3044' GR		10. FIELD AND POOL, OR WILDCAT Brushy Draw-Delaware	
RECEIVED AUG 09 '88 C. C. D. ARIZONA, OFFICE		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18, T-26-S, R-30-E	
		12. COUNTY OR PARISH Eddy	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☒

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

Cleaned out, reperf & acidize  
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

7/28/88 JUNK @ 3370' SLM OR 3374' WLM RE-PERF @ 3321-3345 W/ 2 JSPF. RIH W/ WL SET CIBP SET @ 3370'. RIH W/ FB PKR 3366' TEST CIBP TO 1000# OK. ACDZ PERFS 3321-3345 W/ 1000 GALS's 7-1/2% HCL. EIR INTO PERFS AFTER ACID JOB OF 5 BPM @ 1240#. NEW PBTD 3370'.

VERBAL APPROVAL BY SHANNON SHAW ON 7/25/88.

18. I hereby certify that the foregoing is true and correct

SIGNED Alva Franco

TITLE Accounting Associate

DATE 7/29/88

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

RECEIVED  
AUG 1 9 25 AM '88