

UNITED STATES
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIP
(Other instruction
verse side)

DATE

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM16814

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bedena Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Brushy Draw-Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18, T26S, R30E

12. COUNTY OR PARISH

Eddy

New Mexico

API #30-015-25273

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Salt Water Disposal Well

2. NAME OF OPERATOR

Oryx Energy Company

3. ADDRESS OF OPERATOR

P.O. Box 26300, Oklahoma City, OK 73126-0300

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

L, 660' FWL & 1055' FSW

14. PERMIT NO.

30-015-25273

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3044' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12/11/90 - MIRU Permian WS Rig. ND WH. NU BOP. TIH w/5 1/2" Watson CIBP on 2-7/8" WS & set CIBP @ 3246'. Western spot 10 SX on CIBP. PU w/WS & Circ. hole w/10#/gal mud. POH w/WS/ND BOP & remove slips. Work stretch on Csg. & cut Csg. @ 2450'. Pipe not free. Cut Csg. @ 1800'. Pipe came free. SNFN. Prep to POH. LD Csg. & cont. P&A.

12/12/90 - POH. LD 45 jts 5 1/2" Csg. TIH w/ 2 7/8" WS OE to 3000'. Spot 20 SXS Class "C" CMT 3000-2802'. PU w/WS to 1849'. Western spot 50 sx Class "C" CMT @ 1849'. WOC 2 hrs. TIH w/WS OE & tag TOC @ 1640'. PU w/WS to 384'. Spot 120 SX Class "C" CMT to surface. POH & LD Tbg. ND wellhead. Cut off WH 4'. BGL weld on dry hole marker. Rig down & RR 11:00 p.m.

APPROVED
DATE
SUBJECT

Post ID-1
12-28-90
P4A

18. I hereby certify that the foregoing is true and correct

SIGNED

Jan Stevenson

TITLE Proration Analyst

DATE 9/25/91

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 10/17/91

*See Instructions on Reverse Side