

95F

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for production test, test or re-deepening of a well in a different reservoir. Use APPLICATION FOR PERMITS FOR SUCH PURPOSES)

1. LEASE OR LOCATION AND SERIAL NO.

NM 27647

6. IF INDIAN, ABBREVIATE OR TRIBE NAME

7. UNIT ACQUISITION NAME

8. FARM OR LEASE NAME

EXXON #31 FEDERAL

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Wildcat - Del Norte
11. GEO. T.C.E., M.C., S.S., AND
CIVIL OR AREA

12. COUNTY OR PARCEL ID. CODE

13. DATE

RECEIVED BY
OCT 30 1985
O. C. D.
ARTESIA, OFFICE

1. WELL TYPE GAS OTHER

2. NAME OF OPERATOR
WHITFIELD DRILLING COMPANY, INC.

3. ADDRESS OF OPERATOR
P.O. BOX 729, DENVER, CO 80201
4. LOCATION OF WELL (Give all numbers clearly and include well with any hints required)
100' TND, 1080' ...

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO


SUBSEQUENT REPORT OF

TEST WASTE SHUTOFF
FRACURE TREATMENT
PLUGGING OR ABANDON

FIELD OR ALTER A WELL
SCHEDULE COMPLIANCE
ABANDON

WATER SHUTOFF
FRACURE TREATMENT
PLUGGING OR ABANDON

REPAIRING WELL
ALTERED CEMENT
ALTERED PERMITS



14. REPORT RESULTS OF ANALYSIS COMPLETED ON WELL (Indicate on appropriate box Result and Loss Core)

10/29/85 - Trip in hole open ended with drill pipe to 1080', plug with 4" class 2" cement.
Set Cement plug as follows:
3400-3600' - 200' plug
900-1000' - 100' plug
Trip in hole with drill pipe, set plug 2' 30". Set 80' plug at surface
PLUG ABANDON 10/29/85



Mark Hickey Acting

DATE 10/29/85

For Instructions on Filing See

NM 27647

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED BY
OCT 30 1985
O. C. D.
ARTESIA, OFFICE

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
RHYMES DRILLING COMPANY, INC.

3. ADDRESS OF OPERATOR
P O BOX 729, ROSWELL, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
SE 1/4, NW 1/4, SEC 31, T25S, R30E
1980' FNL, 1980' IWL, EDDY COUNTY, NM

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

EXXON '31' FEDERAL

9. WELL NO.
#1

10. FIELD AND POOL, OR WILDCAT
Wildcat - Delaware

11. SEC., T., R., M., OR BLE. AND SURVEY OR ARSA

Sec 31, T25S, R30E

14. PERMIT NO.
13-2920-84-B

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3096.5 GR

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/05/85 - Trip in hole open ended with drill pipe to 3594', plug with class "C" cement.
Set Cement plugs as follows:
3400-3600' - 200' plug
900-1000' - 100' plug
Trip in hole with drill pipe, tag plug @ 880'. Set 50' plug at surface
PLUG & ABANDON 10/05/85



I hereby certify that the foregoing is true and correct

SIGNED: [Signature]

TITLE: Clerk

DATE: 10/07/85

This space for Federal or State office use

APPROVED BY: [Signature] [Signature]
TITLE: AREA MANAGER, CARLESON RESERVE AREA

DATE: 10 29 85

CONDITIONS OF APPROVAL IF ANY:

*See Instructions on Reverse Side