

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions
versé aide)

Form approved.
Budget: Bureau No. 1004-0135
Expires August 31, 1985

clsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NM 16814	
2. NAME OF OPERATOR Challenger Energy, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR PO Box 1262, Artesia, NM 88211-1262		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FNL 330' FWL Sec. 18, T-26S, R-30E		8. FARM OR LEASE NAME Bedena Federal	
		9. WELL NO. 2	
		10. FIELD AND POOL, OR WILDCAT Brushy Draw-Delaware	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18, T-26S, R-30E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DP, RT, GR, etc.) 3035.5 (GL)	12. COUNTY OR PARISH Eddy	13. STATE NM

RECEIVED BY
MAY 18 1987
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRAC TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANE	☐
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRAC TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☒	ABANDONMENT*	☐
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2/3/87 MIRU pulling unit prepare to perforate
2/4/87 Perforate 3411, 3415, 18, 20 with 4 SPF (16 holes)
3347, 51, 55, 58, 59, 63, 65, 66, 67 with JSPF (9 holes)
2/5/87 Set RBP @ 3500', acidize 3411-20 with 1000 gal 10% acetic acid swab acid w/Trace oil
2/6/87 Swab test 3411-20, trace Oil & gas cut formation water
2/9/87 Set RBP @ 3400', acidize 3347-67 with 1000 gal 10% acetic acid - swab acid
2/10/87 Swab acid and formation water
2/11/87 Swab formation water with trace oil and gas
2/12/87 Reset RBP @ 3450', swab test zones 3347-67 and 3411-20
2/13/87 Swab formation water with trace oil and gas

ACCEPTED FOR RECORD

MAY 8 1987

SJS
CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Craig Huber

TITLE Agent

DATE 5/4/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side