## CRA BLM FORMAT

Well

## APPLICATION FOR SURFACE COMMINGLING, OFF LEASE STORAGE AND MEASUREMENT APPROVAL

## This Format Should Be Attached To A Sundry Notice

To: Bureau of Land Management P. O. Box 1778 Carlsbad, New Mexico 88221-1778

Lauren Tradito

CENTRAL RESOURCES, INC. (Operator's Name) is requesting approval for surface commingling and off-lease storage and measurement of hydrocarbon production from the following formation(s) and well(s) on Federal Lease No. <u>NMNM11039</u>; Lease Name: <u>Brushy Fed. 12A</u>

Well No.	Loc.	Sec.	Twp.	<u>Rng.</u>	Formation
	<u> </u>	12	265	29E	Delaware

with hydrocarbon production from the following formation(s) and well(s) on Federal lease No. <u>NMLC071066</u>; Lease Name: <u>Brushy 12 Fed</u>.

No.	Loc.	<u>Sec.</u>	Twp.	Rng.	Formation
12	<u>N</u>	12	26S 26S	<u>29E</u> 29E	Delaware
3	<u>N</u>	12	26S	29E	(1
4	L	12	26S	29E	11

Production from the wells involved is as follows:

Well Name and No.	BOPD	<u>Oil Gravity</u>	MCFPD
Brushy         Fed.         12A-1           Brushv         12         Fed #1           Brushv         12         Fed #2           Brushv         12         Fed #3           Brushv         12         Fed #4	$\begin{array}{r} 3 \\ 10 \\ 6 \\ 0 \\ 4 \end{array}$	$     \begin{array}{r}         39.1 \\         36.5 \\         38.3 \\         0 \\         38.3 \\         38.3 \\         \end{array} $	

Continued ...