		;				
STATE OF NEW MEXI						
ENERGY AND MINERALS DEP		II CONCEDVA	TION DIVISION			
we, or cortes acceived	<del></del> -		TION DIVISION			Form C-103 .
DISTRIBUTION		P. O. BO				Revised 10-1-2
SANTAFE		SANTA FE, NEW	MEXICO 87501			
FILE	<u> </u>		DECEN	/ED	5a. Indicate Type	of Lease
0.1.0.1.			RECEI	AER	.State X	Fon [
LAND OFFICE	<del>, /</del>				5. State Oil & Ga	Leose No.
OF ENATOR					V-581	1
			WELLS OCT 1	5 '87	TTTTTTT	
S IDO HOT USE THIS FORM	UNDRY NOTICES	AND REPORTS ON	WELLS	,		
USE "LA	PPLICATION FOR PERMIT	_" IFORM C-1011 FOR SUE	PROPESALS.)	<del>- D</del>	7. Unit Agreemen	L Name
01L [V] 6A3 [	7		ARSESIAN			
well Mell	OTHER-		A PARTIE SEPT	. 34	N/A 8, Form or Lease	T
Name of Operator	7				8, rum or Leose	isame .
Corinne Grace					Win Stat	e
Address of Operator					9. Well No.	
P.O. Box 1418,	Carlsbad, N	M 88220		İ	1	
Location of Well					10. Field and Po	oi, et Wildcat
	1000	Monk	660		Und F D	oce Draw
UNIT LETTER	_,1980rc	CT FROM THE WEST	LINE AND 660 F	EET FROM	riririr	THITTITI
THE North LINE	:, SECTION36	томизнір26	S RANGE 30E	НМРМ.		
					77777777	744444
	1//////////////////////////////////////	Elevation (Show a tether	DF, RT, GR, etc.)		12. County	
		3025 GR			Eddy	71111111
Report of ope	erations for	month of Ser	REMEDIAL WORK  COMMENCE DRILLING OPHS.  CASING TEST AND CEMENT 198  OTHER Drilling  ails, and give pertinent dates,  otember, 1987	Oper	ations	Starting any propos
LIIAG	ibit "A" Att	ached				
	* .					•
		•			•	
			•			
			of my benefit due and halfef		<del></del>	
iff. I hereby certify that the In-	<i>1</i> .	e and complete to the best	Of the submitted and periets			
11/1	mille		_		• •	12 07
Polley	Madle.	T17LE	Agent		DATE 10	-T2-8/

CUNDITIONS OF APPROVAL, IF ANYI

## EXHIBIT "A"

## CORINNE GRACE Win State #1 Sec. 36, T-26S, R-30E. Eddy County, New Mexico

- 9-01-87 Clean out fill to 100 Ft.
- 9-02-87 Shut Down.
- 9-03-87 Shut Down.
- 9-04-87 Clean out fill Drill to 102 Ft.
- 9-05-87 Shut Down.
- 9-06-87 Shut Down.
- 9-07-87 Shut Down.
- 9-08-87 Clean out fill to 102 Ft. and drill 2 Ft to 104 Ft.
- 9-09-87 Drill 8 Ft. to 112 Ft.
- 9-10-87 Clean out fill to 112 Ft. and drill 2 Ft. to 114 Ft.
- 9-11-87 Shut Down.
- 9-12-87 Shut Down.
- 9-13-87 Shut Down.
- 9-14-87 Clean out fill to 114 Ft. and drill to 4 Ft. to 118 Ft.
- 9-15-87 Clean out 16 Ft. of fill and drill 4 Ft. to 122 Ft.
- 9-16-87 Shut Down.
- 9-17-87 Shut Down.
- 9-18-87 Clean out 10 Ft. of fill to 122 Ft. and drill 2 Ft. to 124 Ft.
- 9-19-87 Shut Down.
- 9-20-87 Shut Down.
- 9-21-87 Drill to 128 Ft.

- 9-22-87 Drill to 130 Ft.
- 9-23-87 Shut Down.
- 9-24-87 Shut Down.
- 9-25-87 Clean out 12 Ft. of fill to 130 Ft.
- 9-26-87 Shut Down.
- 9-27-87 Shut Down.
- 9-28-87 Clean out 8 Ft. of fill to 130 Ft. Drill 4 Ft to 134 Ft.
- 9-29-87 Clean out 17 fill.
- 9-30-87 Clean out 4 Ft. fill to 134 Ft. and drill 4 ft. to 138 Ft.