

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

1991

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Bettis, Boyle & Stovall ✓

3. Address and Telephone No.

P. O. Box 1240, Graham, TX 76450

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1235' FSL, 1515' FWL, Sec. 10, T25S, R29E, Eddy Co., NM

5. Lease Designation and Serial No.

NMNM15303

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Pickett Draw Fed. #2

9. API Well No.

300152586700S1

10. Field and Pool, or Exploratory Area

Wildcat-Delaware

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WORK PERFORMED

9/17/91 Pulled 2-7/8" tubing and Lokset packer.
9/18/91 Set CIBP above Wolfcamp perfs @ 11,205'.
9/19/91 Pump cmt. plug on top of CIBP 11,205-11,090' (Halliburton) w/ 25 sx.
9/20/91 Set cmt. plug across Top of Liner 10,050-9845' w/ 80 sx.
9/24/91 Set cmt. plug 6090-5956' w/ 45 sx.
9/24/91 Perf 4 sqz. holes @ 5228' and set cmt. retainer @ 5220'.
9/25/91 Attempt to sqz. @ 5228'. Could not pump in.
9/26/91 Perf Delaware 5184-5204' and acidize w/ 2000 gal 7-1/2% acid.
9/26/91 Swab test well. Put well on pump.

PROPOSED WORK → No prior approval required. SJS

1. Put well on pump 2-3 weeks and request test allowable.
2. Frac Delaware and run potential test.

14. I hereby certify that the foregoing is true and correct

Signed Steve Gray Steve Gray Title Petroleum Engineer

Date 9/26/91

(This space for Federal or State office use)

Approved by _____

Title _____

Date _____

Conditions of approval, if any: _____