

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. 30-015-27008

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
V-2372

7. Lease Name or Unit Agreement Name:  
Cactus 16 State

8. Well No. 1

9. Pool name or Wildcat  
N Poker Lake Delaware Pool

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3492' GR

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Ricks Exploration, Inc

3. Address of Operator  
210 Park Ave, STE 3000 Oklahoma City, OK 73102

4. Well Location

Unit Letter C : 330 feet from the north line and 2310 feet from the west line

Section 16 Township 24S Range 31E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐


CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RU PU. LD pump and rods. ND Wellhead. NU BOP. Release tbg anchor. TOO H w/ tbg and anchor
2. RU Wireline. Set CIBP @ 5950'. Dump bail 35' cmt on CIBP.
3. TIH w/ tbg and SSN to 5800'. Displace hole w/ packer fluid. ND BOP. NU wellhead. Press test to 500#.
4. RD PU.

Notify OCD 24 hrs. prior to any work done



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bryan Rother TITLE Engineer DATE 11/9/01

Type or print name Bryan Rother Telephone No. 405/516/1100

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 11-16-01

Conditions of approval, if any: