	Į.		S LAND MANAR	
. Form 3160-5 (June 1990)	DEPARTMENT (O STATES OF THE INTERIOR ID MANAGEMENT	REDEIVED	FORM APPROVED Fudget Bureau No. 1004-0135 Expires: March 31, 1993 S. Lease Designation and Serial No.
Do not use this for	n for proposals to drill o	D REPORTS ON WELLS r to deepen or reentry to ERMIT—" for such propos	a different reservoir.A.	6. If Indian, Allottee or Tribe Name
	SUBMIT IN	TRIPLICATE	(sbad, New	If Unit or CA, Agreement Designation
4. Location of Well (Footage,	Ste 3301, Fort Wor Sec., T., R., M., or Survey Descrip	SE th, TX 76102 (800)	2. EIVED 2. 1. 7. 1993 2 D.	8. Weil Name and No. Poker Lake Unit No. 78 9. API Weil No. 30-015-27536 10. Field and Pool, or Exploratory Area Poker Lake Delaware 11. County or Parish, State
	TEL OI Sec. 25,	1-24-3, K-JU-E		Eddy
12. CHECK AF	PPROPRIATE BOX(s) T	O INDICATE NATURE (OF NOTICE, REPOR	T, OR OTHER DATA
TYPE OF SU	IBMISSION		TYPE OF ACTION	
Notice of II		Abandonment Recompletion Plugging Back		Change of Plans Change of Plans New Construction Non-Routine Fracturing
	A C	Casing Repair Altering Casing Other <u>PROV</u>	DUCTION (Sg.	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completions of Report and Los form)

Completion or Recompletion Report and Log form.)
 Completion or Recompletion Report and Log form.)
 J. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled,
 give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cement did not circulate while cementing the 5.50" casing. A temperature survey was run and found top of cement at appx. 4,270' KB. The 8.625" casing was set at 4,203' KB with cement circulated. The Delaware formation from 4,270' to 4,203' KB does not appear to be productive.
Any fluid present in the interval 4,203' to 4,270' KB is contained between the cement outside the 5.50" casing, the 8.625" casing and the 5.50" casing. The annular area is contained at the surface by the 3000 psig WP "B" section of the well head.

- For this reason, we are requesting approval to defer cementing this section and back up into the 8.625" casing until when the well is plugged. At that time, the 5.50" casing will be cut and pulled from the hole and a cement plug placed in the stub and 200 feet up into the 8.625" casing.

- A schematic well bore diagram depicting the various cement tops and casing seats is attached.

<u></u>					
14. I hereby certify that the foregoing is true and correct Signed	Title Agent for Fortson Oil Company	Date _	. A	1 73/	193
(This space for Federal or State office use)	The Agent for Foreson OIL Company	Date			
Approved by Conditions of approval, if any:	Title	Date _			
	<i></i>		,	•	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly or representations as to any matter within its jurisdiction.	and willfully to make to any department or agency of the United States	any false	, fictitious	or fraudu	ilent stateme

Well: POKER LAKE NO. 78

County: EDDY COUNTY, NEW MEXICO

Objective Zone: DELAWARE



