Form 3160-5 (November 1994)

TED STATES DEPAR'. →NT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil (811 S. 1st Street

3. Division FORM APPROVED OMB No. 1004-0135

SUNDRY NOTICES AND REPORTS ON WELLS

Serial No. NM034963

Do not use this form for proposals to drill or reenter an abandoned well like Form 2000 at 1 the Form 2000 a 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse aids Type of Well Oil Well Gas Well Other 8. Well Name and No. Name of Operator Sundance Federal #11 Merit Energy Company 9. API Well No. Address Phone No. (include area code) 30-015-27578 12222 Merit Dr., Suite 1500, Dallas, TX. 75251 972-383-6569 10. Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) Sand Dunes, West Delaware 1980' FSL & 660' FEL 11. County or Parish, State Sec. 5-T24S-R31E Eddy Co., New Mexico 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair **New Construction** Recomplete Other Add perfs Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operations (clearly state all pertinent det Describe Proposed or Completed Operanous (quarry same as perment quasis, measuring maintains starting uses or any proposal with a performance of all pertinent markers and annex and measured and true vertical depths of all pertinent markers and annex Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 does following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once the string has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operation after the operation of the involved operation. apple open Merit Energy Company proposes to add additional perforatons to the Delaware reservoir. MIRU. POOH w/rods. POOH w/tbg. & downhole equipment. POOH w/4" 1) slotted liner. In unsuccessful, do not add perforations. RBIH w/rods & production equipment. Put well back on production. If successful pulling liner, MIRU perforators. RIH w/csg. gun. Perforate 2) Delaware as follows: 7796' - 7814' (2 spf). 3) Swab well to get test. Acid stimulate as necessary. RIH w/production equipment & put on pump as necessary. State of New Mexico Oil Conservation Division 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Lynne Moon Regulatory Analyst Signature Date 9/1/99 THIS SPACE FOR PEDERAL OR STATE USE ORIG. SGD) GARY GOURLEY Date **OCEUM** ENGINEER Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable tide to those rights in the subject lease which would entitle the applicant to conduct operations thereon.