

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Division
811 S. 1st St.
Albuquerque, NM 87102-2834
87102-2834

FORM APPROVED
Bureau No. 1004-0135
Edition: March 31, 1993
Form Designation and Serial No.
18626

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Enron Oil & Gas Company

3. Address and Telephone No.

P. O. Box 2267, Midland, TX 79702 (915) 694-8228

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330 FSL & 2310 FWL
Sec. 24, T26S, R30E
Unit N

5. If Indian, Allottee or Tribe Name

7. If Unit or CA Agreement Designation

8. Well Name and No.

Palm Springs 24 Federal #1

9. API Well No.

30-015-28358

10. Field and Pool, or Exploratory Area

E Ross Draw, E Del

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☐ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment
☐ Remediation
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recommendation Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2/18/98 RIH w/Alpha CIBP. Set @ 5700'. Delaware perms 5790-5800'.

2/19/98 Spot 35' cmt on top of CIBP. TOC @ 5665'. RU on 5 1/2" csg, PU off slips w/87,000# RIH w/shot and cut csg @ 2943'. Work csg to 150,000# w/no success. RIH and shot csg @ 2073'. Worked csg to 140,000# w/no success. RIH and cut csg @ 2039'-pulled free.

2/20/98 POOH 49jts 5 1/2" J55 LTC csg, RIH w/ 2 7/8" open ended tbg to 3034', spot 35 sx plug from 3034-2934', across attempted cut, (witnessed by BLM rep.) POOH to 2089'. Spot 35 sx plug from 2089-1989 (in and out plug across 5 1/2" cut off @ 2039'). Picked up & cut 8 5/8" csg @ 664'

2/21/98 Spot 50 sx cement plug from 715-613, in and out of 8 5/8"-cut off @ 664'. TIH and tag cmt plug @ 597'. Spot 70 sx cmt plug from 500-378' in and out of 11 3/4" surf csg.

2/24/98 Tag cmt plug @ 425'. POOH LD tbg to 35'. Spotted 20 sx cmt plug from 35'-Surface. Cut off 11 3/4" csg 3' below ground level. Weld on cap and dry hole marker. Filled pit and dug up anchors.

ACCEPTED FOR RECORD
APR 10 1998
(ORIG. SGD.) GARY GOURLEY
BLM

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Agent

Date 3/22/98

(This space for Federal or State official use)

Approved by _____
Conditions of approval, if any:

Title

Date