Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office

DISTRICT I

OIL CONSERVATION DIVISION WELL ARRANGE

P.O. Box 1980, Hobbs NM 88240	P.O. Box 2088 Santa Fe New Mexico 87504-2088		WELL API NO.	_
DISTRICT II			30-015-28576	<u> </u>
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X	FEE 🗌
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	FEE [
SUNDOV NOTIC	ES AND DEDODES ON MEL	1.0	V/////	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name		
(FORM C-101) FOR SUCH PROPOSALS.)			Corral Fly Unit	
1. Type of Well: OIL GAS WELL WELL X	OTHER	/		
2. Name of Operator	OTILK		0 W 11 V	
Santa Fe Energy Resources, Inc.			8. Well No.	
3. Address of Operator			9. Pool name or Wildcat	
550 W. Texas, Suite 1330, Midland, TX 79701			Owen Mesa (Morrow)	
4. Well Location Unit Letter G: 1980	Feet From The North	Line and 198	80 East	
	rect Flom The Hot Cit	Line and198	80 Feet From The East	Line
Section 2	Township 25S Ra	nge 29E	NMPM Eddy	County
	10. Elevation (Show whether	er DF, RKB, RT, GR, etc	:.)	7//////////////////////////////////////
11. Check Appr	////\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	3060' GL		
Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUE			SEQUENT REPORT O	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	; <u> </u>
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDO	ONMENT [
PULL OR ALTER CASING CASING TE		CASING TEST AND CE	MENT JORUE CENVE	<u> </u>
OTHER:		отнея: <u>Set casi</u>	ng	
12. Describe Proposed or Completed Operati	one (Cloarly state all parties at the	7	SEP. 0.7.1005	
work) SEE RULE 1103.	ons (Clearly state all pertinent deta	ills, and give pertinent dat	es, including estimated date of <b>starti</b> ng s	my proposed
3/23/95: TD 8-3/4" hole @ 10,405'. RU and ran 233 jts 7" 26.0# S 9 4 CAN a D Wang and				
5/23/95: 1D 6-3/4 note & 10,405. RU and ran 233 jts /" 26.0# \$=95 & 120 & 180 & 186 & 186 and and set at 10 105' FC @ 10 310' DV tool @ 7017' Computed 1st at a second 05 180 180 180 180 180 180 180 180 180 180				
set at 10,405', FC @ 10,319', DV tool @ 7017'. Cemented 1st stage w/ 850 \$50,650 POZ containing 3/10% D-322 & 6 pps salt. Plug down @ 8:15 a.m. Open DV tool & circ'd 125 sx off				
10WH at 2:45 p.m., Tost returns after 190 pp. of disp. ND % set slips w/ 237 nnn# - Cut off				
' CSQ. ND 5000# BOP and NU IO.000# tubing head and ROP				
3/24/95: Test tbg head to 5000 psi, ok. Install hydril & rotating head. Test choke manifold BOP to 5000 psi, ok. Run temp survey. TOC @ 4010' (TS).				
BOP to 5000 psi, ok. Rui	n temp survey. TOC @	4010' (TS).		
1/20/90: Replace Vibrator	nose. Ku Pu machine	X PII KHA Les	st casing to 2600 psi io	、レーエエロ
3/26/95: Drlg DV tool. To	est casing to zour ps	1, ok. Drig FC	, snoe jt & FS. Drig	formation
I hereby certify that the information above is true a	nd complete to the best of my knowledge	and belief.		
SIGNATURE SIGNATURE	lallough THILE	Sr. Production	n Clerk date <u>9/06/</u>	<del>)</del> 5
TYPE OR PRINT NAME Terry McCullou	gh		TELEPHONE NO.915/6	587.3551
(This space for State Use)	40			<u>8111777 T</u>
•	489 <b>8</b> 9 748 W. 648.			
APPROVED BY DISTRICT DIST		3	SEP 1	1 1995

TITLE