

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38. GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Delaware Mtn. Group	4498	8321	SAND, SHALE, LIME	RUSTLER ANHYDRITE	785	785
				SALT	1117	1117
				BASE SALT	4260	4260
				DELAWARE MTA. GROUP	4498	4498
				BONE SPRING LIME	8370	8370