1. Type of Well

12.

Well

Name of Operator

UNITED STATES FORM APPROVED 18 Gudget Bureau No. 1004-0135 MENT OF THE INTERIOR BURL ... OF LAND MANAGEMENT Expires: March 31, 1993 Lease Designation and Senal No ³⁴NM 693<u>69</u> SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use *APPLICATION FOR PERMIT -* for such proposals 2525272820303 If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Well Name and No Sotol Federal Weil #/ RECEIVED Sonat Exploration Company API Well No OCD - ARTESIA 3. Address and Telephone No. 30 015 28865 110 W. Louisiana, Suite 500, Midland, TX 7970I, 9I5 684-0433 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Mesa Verde (Delaware) SURFACE: 1980 FNL & 1980' FEL 11. County or Parish, State Sec I, T24S, R3IE Eddy County, New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion New Construction X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other: Add perfs & frac Dispose Water 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dniled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work, 2-I3-97: Rig up reverse unit, circulate hole w/2% KCL water, I35 bbls.

2-9-97: Rig up & perforate from 83I4-8320', 4 SPF. Testing tubing.

2-I4-97: Continue to circulate hole, total bbls 2% KCL to recover - 563 bbls.

2-I5-97: Continued in hole w/ 2 7/8" N-80 tubing, screwed into fish @ 6845', attempt to work packer loose, rig up wireline & run free point @ 7160' & 7127', 100% free @ 7064', well began to flow, pumped 48 bbls 2% KCL water. Back off tubing at 7064', TOOH w/wireline. Ran bottom of wash pipe to 6750', pumping 20 bbls KCL down casing. SDON.

2-I7-97: RIH w/2 7/8* new N-80 tubing, tag sand @ 7085'. Break circulation w/I20 bbls 2% KCL, pump to circulate hole clean. Total load to recover from 2-I0-97 acid/frac=9l2 bbls, 2-I3-97=286 bbls, 2-I4-97=403 bbls, 2-I5-97=58 bbls, 2-I7-97=750 bbls, total load to recover through 2-17-97 is 2419 bbls.

2-18-97: Ran tubing SN @ 6530', start to run pump, shut down.

2-I9-97: Put well on pump, rig down equipment.

2-20-97: Well on production.

OCT 2 1 1997 (ORIG_SGD.) GARY GOURLEY

	1	1)
14. The ./		HII
	un Vill	
Signed / (This space for Fe	deral or State office use	e)
, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		-,

Ann E. Ritchie **REGULATORY AGENT** Title

Approved by

Conditions of approval, if any

Date

HAT OCT -9 A 5: 14

ROSWELL OFFICE