Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

**FORM APPROVED** 04 BUM CDA

i		1 f. js	BLM - CRA			
		Fe	bruary	08,	1996	
5.	Lease	Desia	nation	and	Serial	No.

## SUNDRY NOTICES AND REPORTS ON WELLS

LC-061705X A Do not use this form for proposals to drill or to deepen or reentry to a different reservoir 6. If Indian, Allotee or Tribe Name Use "APPLICATION FOR PERMIT" for such proposals SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation 1. Type of Well Poker Lake Unit X Oil Well Gas Well Other 2. Name of Operator JAN 1999 8. Well Name and No. 7 Bass Enterprises Production Company Poker Lake Unit #118 RECEIVED 3. Address and Telephone No. 9. API Well No. OCD - ARTESIA P. O. Box 2760 30-015-29213 Midland, Texas 79702-2760 (915) 683-2 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Poker Lake (Delaware) SW 11. County or Parish, State 760' FSL & 2180' FWL Section 25, T24S-R30E, Unit Letter N Eddy County, New Mexico 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other Add Perfs and Frac Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* Set CIBP @ 7150 9/16/97 RIH w/ 4" casing gun loaded with 19 gram GOEX charges @ 180 degree phased and perf the following interval: 6966-72' (6', 7 holes) 6810-17' (7', 8 holes) Acidize with 1000 gals 7-1/2%HCl acid with additives. Frac with 24,200 gals YF-130 + 10,973# 20/40 Brady Sand. Return well to production. PETER W. CHESTER Set CIBP @ 6750', test to 3000 psi, ok. 2/17/98 Spot 500 gals of 15% NEFE HCI acid with additives across 618 to 6686. RIH with 4" casing gun loaded with 2 JSPF @ 0 degree phased and perforate the following interval: 6606-10' (4', 4 holes) 6672-76' (4', 4 holes) Frac with 23,000 gals SFG-2500 + 4000# 16/30 Brady Sand + 36,000# Resin Coated Sand. JAN 12 1999 Drill out CIBP's @ 6750' and 7150'. 2/19/98 BUREAU OF LAND MANAGEMENT Clean out sand fill to PBTD @ 8090'. ROSWELL RESOURCE AREA Return well to production. 14. I hereby certify that the foregoing is true and correct Signed 4 Tami Wilber **Production Clerk** 12/8/98 (This space for Federal or State office use) Approved by Title Date Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fradulent statements

or representaives as to any matter withing its jurisdiction.

RECEIVED BY

.