

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division  
811 S. 1st Street  
Artesia, NM 88210-2834

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires March 31, 1993

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

J. C. WILLIAMSON TELE: (915) 682-1797

3. Address and Telephone No.

P. O. BOX 16 MIDLAND, TEXAS

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

5880' FNL & 2310' FEL, Sec. 27, T26S, R30E  
Eddy County, New Mexico

5. Lease Designation and Serial No.  
NM0555443

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation  
Ross Draw Unit

8. Well Name and No.

Ross Draw #18

9. API Well No.

30-015-29586

10. Field and Pool, or Exploratory Area

52795 E Ross Dr De

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☒ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The re-working of the Williamson #18 Ross Draw was an attempt to add another sand (5560' to 5600') to the production of this well which is producing from the Getty Sand at 5880' to 6030'.

The attempt failed due to the second sand not responding to perforations and acidizing of the section (no water or oil or gas).

The #18 well has been returned to production from the lower sand where it has been getting it's oil from.



2000 NOV 21 A  
RECEIVED

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Owner/Part Owner

(This space for Federal or State office use)

Approved by  
Conditions of approval, if any:

Title

Date

11-21-00