## SURFACE USE AND OPERATIONS PLAN

### FOR

# TEXACO EXPLORATION AND PRODUCTION, INC.

## ROSS DRAW "25" NO. 1

Located 908.9' FNL & 1186.0' FWL Section 25, Twp. 26 South, Range 29 East, N.M.P.M., Eddy County, New Mexico

LOCATED: 32 miles Southeast of Carlsbad, New Mexico

FEDERAL LEASE NUMBER: NM-41646

LEASE ISSUED: Lease is in a producing status

**ACRES IN LEASE: 320.0 Acres** 

RECORD LESSEE: Texaco Exploration and Production, Inc.

SURFACE OWNERSHIP: USA

**GRAZING PERMITTEE:** Byron Paschal

P.O. Box 992 Pecos, TX 79772

POOL: Ross Draw; Wolfcamp

<u>POOL RULES:</u> Field Rules are for no wells to be located closer than 660' to any quarter section lines and lease lines and 10' from quarter-quarter section lines.

**EXHIBITS:** A. Access Road Map

- B. Lease and Facilities Map
- C. Drilling Rig Layout Diagram
- D. Well Location and Acreage Dedication Plat

#### 1. ACCESS ROADS EXISTING

Exhibit "A" is a portion of a 7.5 minute U.S.G.S. topographic map showing the proposed well site and the existing roads in the area. Point "A" is at the intersection of an existing resource road and