	DEPARTME	TED STATES NT OF THE INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135	
	BUREAU OF LAND MANAGEMENT		Expires: March 31, 1993 5. Lease Designation and Serial No.	
Do not i	use this form for proposals to dr	AND REPORTS ON WELLS ill or to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name	
	Use "APPLICATION FO	DR PERMIT-" for such proposals		
1. Type of Well			7. If Unit or CA, Agreement Designation	
	I Gas			
2. Name of Operator			8. Well Name and No. Bradley 13 Federal #4	
Pogo Producing Company			9. API Well No.	
P. O. Box 10340, Midland, TX 79702-7340 (915)685-8100			30-015-31704	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area Corral Canyon Delaware	
660' FNL & 1980' FEL, Section 13, T25S, R29E			11. County or Parish, State	
			Eddy County, NM	
12.	CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		R OTHER DATA	
·····	TYPE OF SUBMISSION	TYPE OF ACTION		
	Notice of Intent	Abandonment	Change of Plans	
	X Subsequent Report		New Construction	
		Plugging Back Casing Repair	Non-Routine Fracturing	
	Final Abandonment Notice	Altering Casing	U Water Shut-Off	
		\mathbf{X} other Bone Spring Perfs	Dispose Water	
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
13. Describe directiona	Proposed or Completed Operations (Clearly sta ally drilled, give subsurface locations and measu	te all pertinet details, and give pertinent dates, including estimated date of red and true vertical depths for all markders and zones pertinent to this wo	starting any proposed work. If well is	
09/08/01		Acdz w/ 1300 gals 7-1/2% HCL. Swab.	un.)	
09/12/01	Frac 8171'-83' w/ 82,000# 16/30 TLC			
	Acdz 7292'-7310' w/ 1000 gals 7-1/2	x. Perf Bone Spring 7292'-7310' w/ 2 spf. Dumped 35' cmt	on top of CIBP @ 8131'.	
10/18/01		% HCL.		
10/18/01				
10/18/01 10/19/01	Set CIBP @ 7252'. Test to 3000# of	. Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top o	of CIBP @ 7252'.	
10/18/01 10/19/01 10/20/01	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2%	. Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top o	of CIBP @ 7252'.	
10/18/01 10/19/01	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2%	. Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top o	of CIBP @ 7252'.	
10/18/01 10/19/01 10/20/01	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2%	. Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top o	of CIBP @ 7252'.	
10/18/01 10/19/01 10/20/01	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2%	. Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top o	*	
10/18/01 10/19/01 10/20/01	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2%	. Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top o	of CIBP @ 7252'.	
10/18/01 10/19/01 10/20/01 10/23/01	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2% RIH w/ RBP & set @ 5679'. Test to 3	Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top o HCL. 3000# ok. Spot 10' sand on RBP @ 5679'.	RECEIVED OCD ARTESIA	
10/18/01 10/19/01 10/20/01 10/23/01	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2% RIH w/ RBP & set @ 5679'. Test to c	Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top of HCL. 3000# ok. Spot 10' sand on RBP @ 5679'.	RECEIVED OCD ARTESIA	
10/18/01 10/19/01 10/20/01 10/23/01	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2% RIH w/ RBP & set @ 5679'. Test to c	Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top of HCL. 3000# ok. Spot 10' sand on RBP @ 5679'.	RECEIVED OCD ARTESIA	
10/18/01 10/19/01 10/20/01 10/23/01 14. I hereby or Signed (This space for Approved by	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2% RIH w/ RBP & set @ 5679'. Test to c active the foregoing is true and correct active the foregoing is true and correct	Title	RECEIVED OCD ARTESIA OCD ARTESIA Date 12/18/01	
10/18/01 10/19/01 10/20/01 10/23/01 14. I hereby or Signed (This space for Approved by	Set CIBP @ 7252'. Test to 3000# of Acdz 6770'-87' w/ 1000 gals 7-1/2% RIH w/ RBP & set @ 5679'. Test to c	Perf Delaware 6770'-87' w/ 2 spf. Dump 35' cmt on top of HCL. 3000# ok. Spot 10' sand on RBP @ 5679'.	RECEIVED OCD ARTESIA	

•

*See Instruction on Reverse Side