## **Additional Operator Remarks:**

Surface casing to be set +/- 100' above the Salt.

Production casing cement will be brought up at least 500' above the upmost hydrocarbon bearing zone.

Drilling Procedure, BOPE diagram, Anticipated Formation Tops, and Surface Use Plans attached.

This well is located outside the R-111 Potash Area but inside the Secretary's Potash order. There are no potash leases within 1 mile of this location.