N.M. Oil Corn Divinier Form 3160-5 - "NITED STATES FORM APPROVED (November 1994) ENT OF THE INTERIOR DEPAR Budget Bureau No. 1004-0135 Expires November 30 2000 BUREAU OF LAND MANAGEMENT 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NM 89815 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side 7. If Unit or CA/Agreement, Name and/or No. Type of Well \mathbf{x} 8. Well Name and No 2. Name of Operator WEST BRUSHY 4 3 BP AMERICA PRODUCTION COMPANY FEDERAL 9. API Well No. 3a. Address <u>30-015-32196</u> 501 WESTLAKE PARK BLVD, RM 5.172 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) BRUSHY DRAW (DELAWARE) UT.C S4, T26S, R29E, NMPM, EDDY COUNTY, NM 11. County or Parish, State NM CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12 TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other SURFACE Final Abandonment Notice Change Plans Plug and Abandon Temporarily Abandon COMMINGLE PERMIT Convert to Injection Plug Back Water Disposal Describe Proposed or Coommpleted Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) 13. determined that the final site is ready for final inspection.) BP America Production Company requests a new surface commingle permit. See attached for list of leases. Plans are to commingle and to store and measure production off lease and to use an alternate method of measurement. Gas and oil will be sold at the West Brushy 8 Federal lease, Section 8 OCT 2 9 2002 LES BABYAK PETROLEUM ENGINEER I hereby certify that the foregoing is true and corect Title Name (Printed Typed) AMY T REGULATORY COMPLIANCE ANALYST Date 10/22/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Conditions of approval, it say, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false. fictitious or fraudulent statements or representations as to any matter within its jurisdiction.